

# ANNUAL VEHICLE INSPECTION REPORT

## VEHICLE HISTORY RECORD

| REPORT NUMBER | FLEET UNIT NUMBER | DATE      |
|---------------|-------------------|-----------|
| 66681541      | 289 476           | 6/24/2021 |

MOTOR CARRIER OPERATOR

Zico Freight/NCORA ROYAL INC

ADDRESS

6850 W. LD. ST

CITY, STATE, ZIP CODE

CHICAGO 60638

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS

☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

JUGOSLAV KOUACEVIC

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE)

☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

66681541 289 476 6/24/2021 106938

INSPECTION AGENCY/LOCATION (OPTIONAL)

## VEHICLE COMPONENTS INSPECTED

| OK | NEEDS REPAIR | REPAIRED DATE | ITEM   | OK | NEEDS REPAIR | REPAIRED DATE | ITEM  |
|----|--------------|---------------|--|----|--------------|---------------|---|
|    |              |               | <b>1. BRAKE SYSTEM</b>   |    |              |               | e. Pitman Arm   |
|    |              |               | a. Service Brakes  |    |              |               | f. Power Steering   |
|    |              |               | b. Parking Brake System  |    |              |               | g. Ball and Socket Joints   |
|    |              |               | c. Brake Drums or Rotors   |    |              |               | h. Tie Rods and Drag Links  |
|    |              |               | d. Brake Hose  |    |              |               | i. Nuts   |
|    |              |               | e. Brake Tubing  |    |              |               | j. Steering System  |
|    |              |               | f. Low Pressure Warning Device   |    |              |               | <b>8. SUSPENSION</b>  |
|    |              |               | g. Tractor Protection Valve  |    |              |               | a. Axle Positioning Parts   |
|    |              |               | h. Air Compressor  |    |              |               | b. Spring Assembly  |
|    |              |               | i. Electric Brakes   |    |              |               | c. Torque, Radius or Tracking Components  |
|    |              |               | j. Hydraulic Brakes  |    |              |               | <b>9. FRAME</b>   |
|    |              |               | k. Vacuum Systems  |    |              |               | a. Frame Members  |
|    |              |               | l. Antilock Brake System   |    |              |               | b. Tire and Wheel Clearance   |
|    |              |               | m. Automatic Brake Adjusters   |    |              |               | c. Adjustable Axle Assemblies (Sliding Subframes)   |
|    |              |               | <b>2. COUPLING DEVICES</b>   |    |              |               | <b>10. TIRES</b>  |
|    |              |               | a. Fifth Wheels  |    |              |               | a. Steer-Axle Tires   |
|    |              |               | b. Pintle Hooks  |    |              |               | b. All Other Tires  |
|    |              |               | c. Drawbar/Towbar Eye  |    |              |               | c. Speed-Restricted Tires   |
|    |              |               | d. Drawbar/Towbar Tongue   |    |              |               | <b>11. WHEELS AND RIMS</b>  |
|    |              |               | e. Safety Devices  |    |              |               | a. Lock or Side Ring  |
|    |              |               | f. Saddle-Mounts   |    |              |               | b. Wheels and Rims  |
|    |              |               | <b>3. EXHAUST SYSTEM</b>   |    |              |               | c. Fasteners  |
|    |              |               | a. No leaks forward of/directly below the driver/sleeper compartment.  |    |              |               | d. Welds  |
|    |              |               | b. Bus: No leaking/discharging in violation of standard.   |    |              |               | <b>12. WINDSHIELD GLAZING</b>   |
|    |              |               | c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle. |    |              |               | No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).                                |
|    |              |               | <b>4. FUEL SYSTEM</b>  |    |              |               | <b>13. WINDSHIELD WIPERS</b>  |
|    |              |               | a. No visible leak.  |    |              |               | Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective. |
|    |              |               | b. Fuel Tank Filler Cap  |    |              |               | <b>14. MOTORCOACH SEATS</b>   |
|    |              |               | c. Fuel tank securely attached.  |    |              |               | Any passenger seat that is not securely fastened to the vehicle structure.                            |
|    |              |               | <b>5. LIGHTING DEVICES</b>   |    |              |               | <b>15. REAR IMPACT GUARD</b>  |
|    |              |               | All lighting devices and reflectors required by Section 393 shall be operable.                               |    |              |               | In place, securely attached, proper size, proper placement (see 393.86).                              |
|    |              |               | <b>6. SAFE LOADING</b>   |    |              |               | <b>16. OTHER</b>  |
|    |              |               | a. Vehicle parts, load, dunnage, spare tire, etc., secured.  |    |              |               | List any other condition(s) which may prevent safe operation of this vehicle.                         |
|    |              |               | b. Front End Structure   |    |              |               |   |
|    |              |               | c. Intermodal Container Securement Devices   |    |              |               |   |
|    |              |               | <b>7. STEERING MECHANISM</b>   |    |              |               |   |
|    |              |               | a. Steering Wheel Free Play  |    |              |               |   |
|    |              |               | b. Steering Column   |    |              |               |   |
|    |              |               | c. Front Axle Beam/All Other Steering Components   |    |              |               |   |
|    |              |               | d. Steering Gear Box   |    |              |               |   |

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, \_\_\_\_\_ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Pass