## **ANNUAL VEHICLE INSPECTION REPORT**

VEHICLE HISTORY RECORD					
REPORT NUMBER	FLEET UNIT NUMBER				
DATE					

	•				
MOTOR CARRIER OPERATOR  ZIGI FREIGHT INC dba ROYAL3 INC	INSPECTOR'S NAME (PRINT OR TYPE)  JUGOSLAV KOVACEVIC				
ADDRESS 6850 W. 63rd STREET	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.  ☑ YES				
CHICAGO, IL 60638	VEHICLE INDETIFICATION ( ✓ AND COMPLETE) ☐ LIC.PLATE NO. ☑ VIN ☐ OTHER				
VEHICLE TYPE ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)				

VEHICLE TYPE ☐ TRACTOR ☑ TRAILER ☐ TRUCK ☐ BUS INSPECTION AGENCY/LOCATE						INSPECTION AGENCY/LOCATION	(OPTI	ONAL)			
						VEHICLE	COMPONENTS INSPECTED				
ОК	NEEDS REPAIR	REPAIRED DATE	ITEM	ОК	NEEDS REPAIR	REPAIRED DATE	ITEM	ОК	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHEILD GLAZING
			a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc.,				No cracks, discoloration,
			b. Parking Brake System				secured.			N/A	obstacles, etc. (see 393.60 for exceptions).
			c. Brake Drums or Rotors								· ·
			d. Brake Hose				b. Front End Structure				13. WINDSHEILD WIPERS
			e. Brake Tubbing			N/A	c. Intermodal Container Securement Devices			N/A	No missing, Damaged, or
		N/A	<ul> <li>f. Low Pressure Warning</li> <li>Device</li> </ul>				7 CTEEDING NAECHANISMA				inoperable wipers.
_		NI/A	- Toroton Doots ation Males			NI/A	7. STEERING MECHANISM				14. MOTORCOACH SEATS
		N/A	g. Tractor Protection Valve			N/A	a. Steering Wheel Free Play			N/A	Seats securely fastened to the vehicle structure.
		N/A N/A	h. Air Compressor  i. Electric Brakes			N/A	b. Steering Column				15. REAR IMPACT GUARD
		N/A	j. Hydraulic Brakes			N/A	C. Front Axle Beam/All Other Steering Components				13. REAR INFACT GOARD
		N/A	k. Vakum Systems			N/A	d. Steering Gear Box				In place, securely attached, proper size,
		IV/A	I. Antilock Brake System			N/A	e. Pitman Arm	_			proper placement (see 393.86).
			m. Automatic Brake Adjusters			N/A	f. Power Steering				16. OTHER
			2. COUPLING DEVICES			N/A	g. Ball and Socket Joints				List any other condition(s)
		N/A	a. Fifth Wheels			N/A	h. Tie Rods and Drag Links				which may prevent safe
		N/A	b. Pintle Hooks			N/A	i. Nuts				operation of this vehicle.
		N/A	c. Drawbar/Towbar Eye			N/A	j. Streering System				
		N/A	d. Drawbar/Towbar Tongue				8. SUSPENSION				
		N/A	e. Safety Devices				a. Axle Positioning Parts				
		N/A	f. Saddle-Mounts				b. Spring Assembly				
			3. EXHAUST SYSTEM				c. Torque, Radius or Tracking				
			a. No leaks forward of/				Components				
		N/A	directly below the driver/ sleeper compartment.		•		9. FRAME				DAČCED
							a. Frame Members				// LAGGEN //
			b. Bus: No leaking/				b. Tire and Wheel Clearance				
		N/A	discharging in violation of standard.				c. Adjustable Axle				
							Assemblies (Sliding Subframes)				
			<ul> <li>c. Unlikely to burn, char,</li> <li>or damage the electrical</li> </ul>								
		N/A	wiring, fuel supply, or any				10. TIRES				
			combustible part of vehicle.			N/A	a. Steer-Axle Tires				
			4. FUEL SYSTEM				b. All Other Tires				
		N/A	a. No visible Leak.			N/A	c. Speed-Restricted Tires				
_		N/A	b. Fuel tank filler cap				11. WHEELS AND RIMS				
		N/A	c. Fuel tank securely attached.				a. Lock or Side Ring				
			LIGHTING DEVICES     a. All required light/reflectors				b. Wheels and Rims				
			operable.				c. Fasteners				
							d. Welds				
CED	INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: VOK, NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE										

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.