

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

66681507 W94933

DATE 04/22/2024

MOTOR CARRIER OPERATOR

Zigi Freight Inc DBA Royal 3 Inc

ADDRESS

6850 W 63rd ST

CITY, STATE, ZIP CODE

Chicago IL 60638

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

Jugoslav Kovačević

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

16R1P062XNJ324220

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System	✓			b. Front End Structure	✓			13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors	✓			c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose	✓			7. STEERING MECHANISM	✓			14. MOTORCOACH SEATS
✓			e. Brake Tubing	✓			a. Steering Wheel Free Play	✓			Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device	✓			b. Steering Column	✓			15. REAR IMPACT GUARD
✓			g. Tractor Protection Valve	✓			c. Front Axle Beam/All Other Steering Components	✓			In place, securely attached, proper size, proper placement (see 393.86).
✓			h. Air Compressor	✓			d. Steering Gear Box	✓			16. OTHER
✓			i. Electric Brakes	✓			e. Pitman Arm	✓			List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes	✓			f. Power Steering	✓			PASS
✓			k. Vacuum Systems	✓			g. Ball and Socket Joints	✓			
✓			l. Antilock Brake System	✓			h. Tie Rods and Drag Links	✓			
✓			m. Automatic Brake Adjusters	✓			i. Nuts	✓			
✓			2. COUPLING DEVICES	✓			j. Steering System	✓			
✓			a. Fifth Wheels	✓			8. SUSPENSION	✓			
✓			b. Pintle Hooks	✓			a. Axle Positioning Parts	✓			
✓			c. Drawbar/Towbar Eye	✓			b. Spring Assembly	✓			
✓			d. Drawbar/Towbar Tongue	✓			c. Torque, Radius or Tracking Components	✓			
✓			e. Safety Devices	✓			9. FRAME	✓			
✓			f. Saddle-Mounts	✓			a. Frame Members	✓			
			3. EXHAUST SYSTEM				10. TIRES				
✓			a. No leaks forward of/ directly below the driver/sleeper compartment.	✓			a. Steer-Axle Tires	✓			
✓			b. Bus: No leaking/ discharging in violation of standard.	✓			b. All Other Tires	✓			
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			c. Speed-Restricted Tires	✓			
			4. FUEL SYSTEM				11. WHEELS AND RIMS				
✓			a. No visible leak.	✓			a. Lock or Side Ring	✓			
✓			b. Fuel Tank Filler Cap	✓			b. Wheels and Rims	✓			
✓			c. Fuel tank securely attached.	✓			c. Fasteners	✓			
			5. LIGHTING DEVICES				d. Welds	✓			
✓			All required lights/reflectors operable.	✓				✓			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.