

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER	DATE
66681542	H03263	6/26/2024

MOTOR CARRIER OPERATOR

Zigi Freight Inc DBA ROYAL INC

ADDRESS

6850 W 63 RD ST

CITY, STATE, ZIP CODE

CHICAGO IL 60638

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS

☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

JUGOSLAV KOVACEVIC

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE)

☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 5V8VC5320RM409996

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				e. Pitman Arm
			a. Service Brakes				f. Power Steering
			b. Parking Brake System				g. Ball and Socket Joints
			c. Brake Drums or Rotors				h. Tie Rods and Drag Links
			d. Brake Hose				i. Nuts
			e. Brake Tubing				j. Steering System
			f. Low Pressure Warning Device				8. SUSPENSION
			g. Tractor Protection Valve				a. Axle Positioning Parts
			h. Air Compressor				b. Spring Assembly
			i. Electric Brakes				c. Torque, Radius or Tracking Components
			j. Hydraulic Brakes				9. FRAME
			k. Vacuum Systems				a. Frame Members
			l. Antilock Brake System				b. Tire and Wheel Clearance
			m. Automatic Brake Adjusters				c. Adjustable Axle Assemblies (Sliding Subframes)
			2. COUPLING DEVICES				10. TIRES
			a. Fifth Wheels				a. Steer-Axle Tires
			b. Pintle Hooks				b. All Other Tires
			c. Drawbar/Towbar Eye				c. Speed-Restricted Tires
			d. Drawbar/Towbar Tongue				11. WHEELS AND RIMS
			e. Safety Devices				a. Lock or Side Ring
			f. Saddle-Mounts				b. Wheels and Rims
			3. EXHAUST SYSTEM				c. Fasteners
			a. No leaks forward of/directly below the driver/sleeper compartment.				d. Welds
			b. Bus: No leaking/discharging in violation of standard.				12. WINDSHIELD GLAZING
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			4. FUEL SYSTEM				13. WINDSHIELD WIPERS
			a. No visible leak.				Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
			b. Fuel Tank Filler Cap				14. MOTORCOACH SEATS
			c. Fuel tank securely attached.				Any passenger seat that is not securely fastened to the vehicle structure.
			5. LIGHTING DEVICES				15. REAR IMPACT GUARD
			All lighting devices and reflectors required by Section 393 shall be operable.				In place, securely attached, proper size, proper placement (see 393.86).
			6. SAFE LOADING				16. OTHER
			a. Vehicle parts, load, dunnage, spare tire, etc., secured.				List any other condition(s) which may prevent safe operation of this vehicle.
			b. Front End Structure				
			c. Intermodal Container Securement Devices				
			7. STEERING MECHANISM				
			a. Steering Wheel Free Play				
			b. Steering Column				
			c. Front Axle Beam/All Other Steering Components				
			d. Steering Gear Box				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

Pass

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.