

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

67129235

#03250

DATE

01/14/25

MOTOR CARRIER OPERATOR

Zigi Freight Inc dba Royal 3 Inc

ADDRESS

6850 W. 68th St.

CITY, STATE, ZIP CODE

Chicago, IL 60637

VEHICLE TYPE ☐ TRACTOR ☒ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

Jugoslav Karacenic

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			b. Parking Brake System	☒			b. Front End Structure	☒			13. WINDSHIELD WIPERS
☒			c. Brake Drums or Rotors	☒			c. Intermodal Container Securement Devices	☒			No missing, damaged, or inoperable wipers.
☒			d. Brake Hose							14. MOTORCOACH SEATS	
☒			e. Brake Tubing							Seats securely fastened to the vehicle structure.	
☒			f. Low Pressure Warning Device							15. REAR IMPACT GUARD	
☒			g. Tractor Protection Valve							In place, securely attached, proper size, proper placement (see 393.86).	
☒			h. Air Compressor							16. OTHER	
☒			i. Electric Brakes							List any other condition(s) which may prevent safe operation of this vehicle.	
☒			j. Hydraulic Brakes								
☒			k. Vacuum Systems								
☒			l. Antilock Brake System								
☒			m. Automatic Brake Adjusters								
			2. COUPLING DEVICES								
☒			a. Fifth Wheels								
☒			b. Pintle Hooks								
☒			c. Drawbar/Towbar Eye								
☒			d. Drawbar/Towbar Tongue								
☒			e. Safety Devices								
☒			f. Saddle-Mounts								
			3. EXHAUST SYSTEM								
☒			a. No leaks forward of/ directly below the driver/sleeper compartment.								
☒			b. Bus: No leaking/discharging in violation of standard.								
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.								
			4. FUEL SYSTEM								
☒			a. No visible leak.								
☒			b. Fuel Tank Filler Cap								
☒			c. Fuel tank securely attached.								
			5. LIGHTING DEVICES								
☒			All required lights/reflectors operable.								
			8. SUSPENSION								
☒			a. Axle Positioning Parts								
☒			b. Spring Assembly								
☒			c. Torque, Radius or Tracking Components								
			9. FRAME								
☒			a. Frame Members								
☒			b. Tire and Wheel Clearance								
☒			c. Adjustable Axle Assemblies (Sliding Subframes)								
			10. TIRES								
☒			a. Steer-Axle Tires								
☒			b. All Other Tires								
☒			c. Speed-Restricted Tires								
			11. WHEELS AND RIMS								
☒			a. Lock or Side Ring								
☒			b. Wheels and Rims								
☒			c. Fasteners								
☒			d. Welds								

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.