ANNUAL VEHICLE INSPECTION REPORT

VE		
REPORT NUMBER	FLEET UNIT NUMBER	DATE
610483911	PTLZ 242143	05/29/2

						0 100 5			
MOTOR CARRIER OPERATOR			INSPECTOR'S NAME (PRINT OR TYPE)						
Fra SpEdit I'C tha Royal 3 MC				JUGOSCAV KOVACEVIC					
ADDRESS ()			THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.						
MOTOR CARRIER OPERATOR Z(g, FREGIST LUC HA Poyal 3 Inc. ADDRESS 6850 W- 6373 St. CITY, STATE, ZIP CODE CLI COJO // 60638			'EY ÉS						
CITY, STATE, ZIP CODE			VEHICLE IDENTIFICATION (✓ AND COMPLETE)						
C/11 cayo 1/2 60638			□ LIC. PLATE NO. ♥ OTHER						
VEHICLE TY	PE D TE	RACTOR HTRAILER TRUCK BUS	INSPECTION AGENCY/LOCATION (OPTIONAL)						
	□ (OTHER)								
					DEATED				
		VEHICLE COMPON	ΕN	18	INS	SPECTED			
OK NEEDS	REPAIRED DATE	ITEM		NEEDS REPAIR	REPAIRED DATE	ITEM			
1	DATE	1. BRAKE SYSTEM				e. Pitman Arm			
9		a. Service Brakes				f. Power Steering			
/	9	b. Parking Brake System		F	Λ	g. Ball and Socket Joints			
0		c. Brake Drums or Rotors				h. Tie Rods and Drag Links			
-		d. Brake Hose		V	10	i. Nuts			
0		e. Brake Tubing				j. Steering System			
V						8. SUSPENSION			
V		f. Low Pressure Warning Device g. Tractor Protection Valve	V			a. Axle Positioning Parts			
			0			b. Spring Assembly			
1111		h. Air Compressor				c. Torque, Radius or Tracking Components			
MID		i. Electric Brakes				9. FRAME			
		j. Hydraulic Brakes							
./		k. Vacuum Systems	V			a. Frame Members			
V .		I. Antilock Brake System	0			b. Tire and Wheel Clearance			
V		m. Automatic Brake Adjusters	-			c. Adjustable Axle Assemblies (Sliding Subframes)			
		2. COUPLING DEVICES				10. TIRES			
NA		a. Fifth Wheels	-	.11	_				
		b. Pintle Hooks		NI	1	a. Steer-Axle Tires			
U		c. Drawbar/Towbar Eye	0	110		b. All Other Tires			
0		d. Drawbar/Towbar Tongue	1	110		c. Speed-Restricted Tires			
		e. Safety Devices	. ,			11. WHEELS AND RIMS			
NA		f. Saddle-Mounts	0			a. Lock or Side Ring			
		3. EXHAUST SYSTEM	C			b. Wheels and Rims			
		 a. No leaks forward of/directly below the 	0			c. Fasteners			
		driver/sleeper compartment.				d. Welds			
		b. Bus: No leaking/discharging in violation				12. WINDSHIELD GLAZING			
11/1		of standard.		111		No cracks, discoloration, obstacles,			
11/1	+	 c. Unlikely to burn, char, or damage the 		1/7		etc. (see 393.60 for exceptions).			
. 1		electrical wiring, fuel supply, or any				13. WINDSHIELD WIPERS			
		combustible part of vehicle.	/	14	1	Any power unit that has an inoperative wiper, or			
		4. FUEL SYSTEM	P	V		missing or damaged parts that render it ineffective.			
		a. No visible leak.		,		14. MOTORCOACH SEATS			
.1	10	b. Fuel Tank Filler Cap	1/	11		Any passenger seat that is not securely			
N	1,	c. Fuel tank securely attached.	1	IM		fastened to the vehicle structure.			
		5. LIGHTING DEVICES				15. REAR IMPACT GUARD			
		All lighting devices and reflectors required by		/		In place, securely attached, proper size,			
		Section 393 shall be operable.				proper placement (see 393.86).			
9.76		6. SAFE LOADING		and the same		16. OTHER			
11/1		 a. Vehicle parts, load, dunnage, spare 				List any other condition(s) which may			
Y/F	7	tire, etc., secured.				prevent safe operation of this vehicle.			
V		b. Front End Structure							
NIA		c. Intermodal Container Securement Devices		100					
		7. STEERING MECHANISM				VASS.			
		a. Steering Wheel Free Play							
11.	1	b. Steering Column				V (.)			
	10	c. Front Axle Beam/All Other Steering Components				5			
9	1	d. Steering Gear Box							
INSTRUC	INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: VALVE OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE								