## **ANNUAL VEHICLE INSPECTION REPORT**

VEHICLE H	IISTORY RECORD		
REPORT NUMBER	FLEET UNIT NUMBER		
67129236	PTC2244743		
DATE 10/29	1/29		

MOTOR CARRIER OPERATOR  Zigi Przight Inc Ibn loyal 3 inc	INSPECTOR'S NAME (PRINT OR TYPE)  JUYOS LATV LOWNERVC			
6850 W. 6314 St.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.			
Chicago LL 60638	VEHICLE IDENTIFICATION ( AND COMPLETE) LIC. PLATE NO. 1991 OTHER 3#3 V532 X8F S119 298 INSPECTION AGENCY/LOCATION (OPTIONAL)			
VEHICLE TYPE ☐ TRACTOR ☐ TRACE ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)			

NEEDS REPAIRED DATE	ITEM	OK NEEDS REPAIRED DATE	ITEM	OK NEEDS REPAIRED DATE	ITEM
	I. BRAKE SYSTEM		6. SAFE LOADING		12. WINDSHIELD GLAZING
	a. Service Brakes b. Parking Brake System c. Brake Drums or Rotors d. Brake Hose		<ul><li>a. Vehicle parts, load, dunnage, spare tire, etc., secured.</li><li>b. Front End Structure</li><li>c. Intermodal Container</li></ul>		No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).  13. WINDSHIELD WIPERS  No missing, damaged, or
10.00	e. Brake Tubing f. Low Pressure Warning		Securement Devices 7. STEERING MECHANISM		inoperable wipers.  14. MOTORCOACH SEATS
	Device g. Tractor Protection Valve h. Air Compressor i. Electric Brakes j. Hydraulic Brakes k. Vacuum Systems l. Antilock Brake System		a. Steering Wheel Free Play b. Steering Column c. Front Axle Beam/All Other Steering Components d. Steering Gear Box e. Pitman Arm		Seats securely fastened to the vehicle structure.  15. REAR IMPACT GUARD In place, securely attached, proper size, proper placement (see 393.86).
2	m. Automatic Brake Adjusters  COUPLING DEVICES  a. Fifth Wheels b. Pintle Hooks c. Drawbar/Towbar Eye d. Drawbar/Towbar Tongue		e. Pitman Arm f. Power Steering g. Ball and Socket Joints h. Tie Rods and Drag Links i. Nuts j. Steering System 8. SUSPENSION		List any other condition(s) which may prevent safe operation of this vehicle.
	e. Safety Devices f. Saddle-Mounts  B. EXHAUST SYSTEM a. No leaks forward of/ directly below the driver/ sleeper compartment.	4	<ul> <li>a. Axle Positioning Parts</li> <li>b. Spring Assembly</li> <li>c. Torque, Radius or Tracking Components</li> <li>9. FRAME</li> <li>a. Frame Members</li> </ul>		Pass
	<ul> <li>b. Bus: No leaking/ discharging in violation of standard.</li> <li>c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.</li> </ul>	4	b. Tire and Wheel Clearance c. Adjustable Axle     Assemblies (Sliding     Subframes)  10. TIRES		
	a. No visible leak. b. Fuel Tank Filler Cap c. Fuel tank securely attached. b. LIGHTING DEVICES		a. Steer-Axle Tires b. All Other Tires c. Speed-Restricted Tires 11. WHEELS AND RIMS a. Lock or Side Ring b. Wheels and Rims		
	All required lights/reflectors operable.	0	c. Fasteners d. Welds		

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.