

DRIVER/VEHICLE INSPECTION REPORT (Driver Copy)



PA State Police - Commercial Vehicle Safety Div.  
1800 Herr Street (Text Bldg)  
Harrisburg, PA 17103-1540  
Email: RA-SPPSPReportCent@pa.gov  
Data Challenges: http://data.challenges.pa.gov  
For more information about this report or the  
motor carrier safety regulations, visit our  
website at http://cdv.pa.gov

Office No 12832	Office Name CHRISTOPHER FOULK
Date 05/22/2024	Time 09:55
Vehicle Type 2 - INTRASTATE	Inspection Type 3 - DRIVER/VEHICLE INSPECTION
Count Number 16	Count Number 398
Location Description ON W 1ST AVE AT ITS INTERSECTION WITH S LIMESTONE RD	
File No 1	Case Number PA 2024-682268

DRIVER	
Driver Name Last SALAZAR CORTEZ	Driver Name First JOSE
Address 4409 W 88TH ST BLOOMINGTON MN 55437	
State of License MN	Date of Birth 12/11/1962
Class of License A	Accident/No. Administrative NO

CARRIER	
Motor Carrier Name RUI TRANSPORTATION INC	
Address 6326 LEDLAINE AVE BURBANK IL 60469-2734	
U.S. DOT Number 03118082	Phone Number (708) 303-8180

VEHICLES	
Vehicle 1 License Number 001 845	Vehicle 1 Year 2020
Vehicle 1 Make MACK	Vehicle 1 Type TT
Vehicle 1 License Code L	Vehicle 1 License Number P1181462
Vehicle 1 GVWR 83,200	
Vehicle 2 License Number 002 PFL232182	
Vehicle 2 Year 2023	Vehicle 2 Make MYR
Vehicle 2 Type ST	Vehicle 2 License Code TH
Vehicle 2 License Number 325948T	Vehicle 2 GVWR 88,000

LOAD	
Origin City LANCASTER	State PA
Destination City PARKESBURG	State PA
Product Type NO	Product Code NO
Product Name NO	Product Code NO
Product Weight NO	Product Code NO

RESTRICTIONS	
Restriction Code 98.2	Restriction Description D - DRIVER
Restriction Code NO	Restriction Description NO

COMMENTS	
Empty at time of inspection.	
Driver related driving empty from Lancaster PA to Victory Breaing in Parkesburg PA for a pickup. Observed traveling westbound on W. 1st Ave. This road is a restricted roadway. 1st Ave posted with sign prohibiting trailers 102' in width over 38.5' in length. Trailer in this combination is 102' wide 83' long.	
CDLIS check completed.	

OUT OF SERVICE SIGNATURES	
Driver/Vehicle Out of Service Notice	
All violations on this report which are not designated as "out of service" must be corrected in accordance with the out of service statement listed on the report.	

Inspector's Signature [Signature]	Inspector's Name 12832
Date 05/22/2024	Time 13:28

RETURN ADDRESS	
Return Address: [Address]	

MOTOR CARRIER	
The undersigned certifies that all violations on this report have been corrected and will not be subject to further action.	

Signature of Carrier Officer [Signature]	Date 5/27/24
---	-----------------



PA17 2041 4348



PA 2024-662268



**Safety Department** <safety@rtbrz.com>  
to RA-SPPSPReportCert

11:50 AM (0 minutes ago)



Hello,

Please find attached signed inspection form.

**Safety Department**  
**Riki Transportation Inc dba BRZ**

MC#086875

8225 Leclaire Ave,  
Burbank, IL 60459

**Phone::** (708) 303-5150

**Email:** [safety@rtbrz.com](mailto:safety@rtbrz.com)

One attachment • Scanned by Gmail

