

DRIVER/VEHICLE EXAMINATION REPORT



South Dakota Highway Patrol
District 4 Headquarters
118 West Capitol Ave
Pierre, SD 57501
Phone: 605-224-7364 Fax: 605-773-7144
Email/Web: sdtruckinfo.sd.gov

Report Number: SD5700000818
Inspection Date: 01/26/2024
Start: 08:46 AM CST End: 10:05 AM CST
Inspection Level: I
HM Inspection Type: None

ZIGI FREIGHT INC
6850 W 63RD STREET
CHICAGO, IL, 60638
dba: ROYAL3 INC
USDOT#: 2828543
MC/MX#:
State#:
Phone#: 630-4857370
Fax#: 630-4856980

Driver: MODICA, CARL, FRANK JR
License# A3795707
State# CA
Date of Birth# 10/22/1970
CoDriver:
License#
State#
Date of Birth#

Location: Sisseton SD
MilePost: 235
Highway: I-29 SB
County: Roberts
Shipper: DAKOTA SPECIALTY MILLING INC
Bill of Lading: 53214
Origin: FARGO, ND, US
Destination: LAREDO, TX, US
Cargo: MULTI GRAIN BLEND

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	PT150993	749	3AKJHDDR2PSNM3960	52,300				
2	ST	HYST	2024	TN	419081T	PTLZ242141	3H3V532K6RS118196	68,000			33738155	

BRAKE MEASUREMENTS

Steer Axle	Yes	No	No	No	No
Chamber	Disc	Disc	Disc	CLAMP - 30-E	CLAMP - 30-E
Right	N/A	N/A	N/A	1 1/4	1 1/4
Axle	1	2	3	4	5
Left	N/A	N/A	N/A	1 1/4	1

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Vio Code	Section	Unit	OOS	Citation #	Verify	Violations Discovered
393.75A3-TAOL	393.75(a)(3)	1	Y	WARNING	A	Tires - All others, leaking or inflation less than 50% of the maximum inflation pressure. AXLE 2 INSIDE LEFT IS FLAT. OFF BEAD

Special Checks:

E Screen

Pursuant to authority contained in Title 49, Code of Federal Regulations, Section 396.9(c), I hereby declare vehicles with defects followed by an "Y" in the "Out of Service" column in the violations discovered section of this report OUT OF SERVICE. No person shall remove the out of service stickers applied to these vehicles, or operate such vehicles until the out of service defects have been repaired and the vehicles have been restored to safe operating condition.

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. False certifications of the required repairs are required to be prosecuted with penalties up to \$10,000.

Signature Of Repairer X: [Signature] Facility: Twin Valley Tire Date: 1-26-24

Safety manager
02/07/24.

Report Prepared By:
KEVIN VALNES

Badge #:
570

Copy Received By:
CARL FRANK JR MODICA

Page 1 of 2



2828543 SD SD5700000818