

DRIVER/VEHICLE EXAMINATION REPORT



DPS Minnesota State Patrol
Commercial Vehicle Section D4700
1110 Centre Pointe Curve Suite 410
Mendota Heights, MN 55120-4152
Phone: 651-350-2000
Email/Web: <https://dps.mn.gov/divisions/msp/commercial-vehicles>

Report Number: MN0548000242
Inspection Date: 06/29/2024
Start: 09:25 AM CDT End: 10:25 AM CDT
Inspection Level: I
HM Inspection Type: None

ZIGI FREIGHT INC
6850 W 63RD STREET
CHICAGO, IL 60638
dba: ROYAL3 INC
USDOT#: 2828543
MC/MX#: _____
State#: _____
Phone#: 6304857370
Fax#: 6304856980

Driver: Carrion Victoriano, Amaury
License# C651000862190
State# FL
Date of Birth# 06/19/1986
CoDriver: _____
License# _____
State# _____
Date of Birth# _____

Location: Worthington
MilePost: 46
Highway: I-90 EB
County: NOBLES
Shipper: AMERICAN COLLOID CO.
Bill of Lading: 50386310
Origin: COLONY, WY, US
Destination: ALLENTOWN, PA, US
Cargo: CLAY-BENTONITE-GROUND

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	P1150992	748	3AKJHHD6PSNM3959	52,500				
2	ST	GDAN	2022	ME	451990Z		1GR1P0629NJ324225	68,000				

BRAKE MEASUREMENTS

Steer Axle	Yes	No	No	No	No
Chamber	Disc	Disc	Disc	CLAMP - 30-E	CLAMP - 30-E
Right	N/A	N/A	N/A	7/8	1
Axle	1	2	3	4	5
Left	N/A	N/A	N/A	7/8	3/4

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Vio Code	Section	Unit	OOS	Citation #	Verify	Violations Discovered
393.45B2-B	393.45(b)(2)	2	N	NONE	N	Air Brake - Hose/tubing damaged or not secured: 1101 - AXLE 5 LEFT BRAKE CHAMBER HOSES CHAFFING AGAINST BOTTOM AIR RESERVOIR TANK (WEAR EXTENDS THROUGH OUTER PROTECTIVE MATERIAL INTO OUTER COVER)

Special Checks:

Size and weight

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. False certifications of the required repairs are required to be prosecuted with penalties up to \$10,000.

Signature Of Repairer X: _____ Facility: _____ Date: _____

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. [49 CFR 396.9(d)(1)]
NOTE TO MOTOR CARRIERS: Within fifteen (15) days following the date of this inspection, the motor carrier or intermodal equipment provider shall: (1) Certify that all violations noted have been corrected by completing the signature portion of this form; and (2) Retain a copy at the motor carrier's principal place of business, or where the vehicle is housed, for twelve (12) months from the date of the inspection. The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with all applicable federal and state regulations.

Signature Of Motor Carrier Official X: _____ Date: _____

Other Driver / Carrier Notifications

To dispute violations or information on this inspection, please use the following website: <https://DataQs.FMCSA.dot.gov>

Report Prepared By:
TSOT Jeff Stearns

Badge #:
0548

Copy Received By:
AMAURY CARRION VICTOR...

Page 1 of 1



2828543 MN MN0548000242

X

X