

#762 Heriz David Rivero

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 3.0.0.17

Public Utilities Commission of Ohio
180 East Broad Street
Transportation Department
Columbus, OH 43215
Phone: (614)466-0429 Fax: (614)752-9274

Report Number: OH3266011247
Inspection Date: 01/24/2024
Start: 01:32 PM ET End: 1:55:46 PM ET
Inspection Level: III - Driver Only
HM Inspection Type: None

ZIGI FREIGHT INC
6850 W 63RD STREET
CHICAGO, IL 60638
USDOT#: 02828543 Phone#: (630)485-7370
MC/MX#: 944686 Fax#:
State#:

Driver: RIVERO PEREZ, HERIZ D
License#: R161324980050 State: FL
Date of Birth: 01/05/1998
CoDriver:
License#: State:
Date of Birth:

Location: PREBLE SCALES
Highway: IR70
County: PREBLE, OH

MilePost: 1 Shipper: INTERTAPE POLYMER / DANVILLE RD
Origin: NEENAH, WI Bill of Lading: GW241925
Destination: DANVILLE, VA Cargo: GENERAL FREIGHT

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	P1173996	762	3AKJHHR9PSUA1598	52,500			
2	ST	GDAN	2022	ME	451985Z	W94933	1GR1P062XNJ324220	68,000			

BRAKE ADJUSTMENTS No Brake Measurements Required For Level 3

VIOLATIONS

Vio Code	Section	Unit OOS	Citation #	Verify	Crash	Violations Discovered
395.15G02	395.15(g)(2)	D N		N	N	Driver failed to have on-board a CMV a sufficient supply of blank records of duty status graph-grids. No blank Drivers Records of Duty Status Graph Grids in CMV.

HazMat: No HM Transported.

Placard: No Cargo Tank:

Special Checks: No Data for Special Checks.

State Information:

FMCSA Credentials Verified(Y/N): Y, CDL Verified(Y/N): Y, FMCSA OOS Order Issued(Y/N): N, For-Hire Carrier: Y, Reason Code: ISSS, Driver Address Verified(Y/N): Y, Driver Address: 2130 CASCADES BLVD UNIT 101, Driver City: KISSIMMEE, Driver State: FL, Driver Zip: 34741-3476, Photos Taken(Y/N): Y,

[Signature]

Safety manager
01/29/2024.

Report Prepared By:
MCEI M. ELKINS

Badge #:
3266

Copy Received By:
HERIZ RIVERO PEREZ

Page 1 of 2



02828543 OH OH3266011247