

## DRIVER/VEHICLE EXAMINATION REPORT



Washington State Patrol  
SPOKANE POE  
PO Box 42614  
Olympia, WA 98504-2614  
Phone: (360) 596-3815  
Email/Web: www.wsp.wa.gov

Report Number: WAX805006402  
Inspection Date: 08/28/2024  
Start: 05:17 PM PDT End: 06:08 PM PDT  
Inspection Level: I  
HM Inspection Type: None

RIKI TRANSPORTATION INC  
8225 LECLAIRE AVE  
BURBANK, IL, 60459  
dba: BRZ  
USDOT#: 3119062  
MC/MX#:  
State#:  
Phone#: 7083035150  
Fax#:

Driver: Bayard, Duthene  
License# B630160762441  
State# FL  
Date of Birth# 07/04/1976  
CoDriver:  
License#  
State#  
Date of Birth#

Location: Spokane Port of Entry  
MilePost: 298  
Highway: I-90 WB  
County: Spokane  
Shipper: Pella Corporation  
Bill of Lading: None  
Origin: MINNEAPOLIS, MN, US  
Destination: PORTLAND, OR, US  
Cargo: Plastic Articles

## VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	P954545	600	3AKJHHDRIPSUA1594	53,000				094676
2	ST	GDAN	1988	TN	U769070	289470	1GRAP062XTT106132	65,000			34345080	

## BRAKE MEASUREMENTS

Steer Axle	Yes	No	No	No	No
Chamber	Disc	Disc	Disc	CLAMP - 30-E	CLAMP - 30-E
Right	N/A	N/A	N/A	3/4	1
Axle	1	2	3	4	5
Left	N/A	N/A	N/A	3/4	11/8

## VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Vio Code	Section	Unit	OOS	Citation #	Verify	Violations Discovered
393.88	393.88	1	N		U	Television/video display device - Improperly located: Driver displaying a video on tablet sitting on dash AND visible to the driver while operating the CMV.
395.20BELDNV	395.20(b)	D	N		N	HOS (ELD) - The ELD display screen is not viewable by an authorized official without entering the CMV: ELD (tablet) secured to driver dash and unable to be moved to be seen from outside CMV w/o entering the CMV.
395.8A	395.8(a)	D	N		N	HOS (Form) - Paper Log/Logging Programs Form and Manner: Violation Date: 08/27/2024; 395.8(h)(1): Driver improperly used OFF DUTY status when resting in SB during trip.
393.75A3-TAOL	393.75(a)(3)	1	Y		N	Tires - All others, leaking or inflation 50% or less than of the maximum inflation pressure: Axle 3 left inside tire has bolt in tread and tire off rim AND unable to maintain inflation pressure. (Flat Tire)

## Special Checks:

E-Screen, Size and weight

VIOLATIONS MARKED AS OUT OF SERVICE (OOS) MUST BE REPAIRED BEFORE VEHICLE/S CAN BE OPERATED. IF OOS FOR BRAKES ADJUSTMENT, ALL BRAKES MUST BE WITHIN PROPER ADJUSTMENT LIMITS BEFORE VEHICLE/S CAN BE OPERATED.

Report Prepared By:  
J. St. Laurent

Badge #:  
X805

Copy Received By:  
DUTHENE BAYARD

Page 1 of 2



3119062 WA WAX805006402



## DRIVER/VEHICLE EXAMINATION REPORT



Washington State Patrol  
SPOKANE POE  
PO Box 42614  
Olympia, WA 98504-2614  
Phone: (360) 596-3815  
Email/Web: www.wsp.wa.gov

Report Number: WAX805006402  
Inspection Date: 08/28/2024  
Start: 05:17 PM PDT End: 06:08 PM PDT  
Inspection Level: I  
HM Inspection Type: None

RIKI TRANSPORTATION INC  
8225 LECLAIRE AVE  
BURBANK, IL, 60459  
dba: BRZ  
USDOT#: 3119062  
MC/MX#:  
State#:  
Phone#: 7083035150  
Fax#:

Driver: Bayard, Duthene  
License# B630160762441  
State# FL  
Date of Birth# 07/04/1976  
CoDriver:  
License#  
State#  
Date of Birth#

Location: Spokane Port of Entry  
MilePost: 298  
Highway: I-90 WB  
County: Spokane  
Shipper: Pella Corporation  
Bill of Lading: None  
Origin: MINNEAPOLIS, MN, US  
Destination: PORTLAND, OR, US  
Cargo: Plastic Articles

I CERTIFY THAT ALL MECHANICAL VIOLATIONS WERE

REPAIRED

Signature Of Repairer X: \_\_\_\_\_

Facility: \_\_\_\_\_

Date: \_\_\_\_\_

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. [49 CFR 396.9(d)(1)]

NOTE TO MOTOR CARRIERS: --- TRUCKERS AGAINST TRAFFICKING --- If you suspect human trafficking, please contact 9-1-1 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.

THE UNDERSIGNED CERTIFIES THAT ALL

VIOLATIONS NOTED ON THIS REPORT HAVE BEEN CORRECTED AND ACTION HAS BEEN TAKEN TO ASSURE COMPLIANCE WITH ALL APPLICABLE FEDERAL AND STATE REGULATIONS. WITHIN FIFTEEN (15) DAYS FOLLOWING THE DATE OF INSPECTION, THE MOTOR CARRIER OR INTERMODAL EQUIPMENT PROVIDER SHALL: (1) CERTIFY THAT ALL VIOLATIONS NOTED HAVE BEEN CORRECTED BY COMPLETING THE "SIGNATURE OF CARRIER/INTERMODAL EQUIPMENT PROVIDER OFFICIAL, TITLE, AND DATE SIGNED" PORTION OF THE FORM; AND (2) RETAIN A COPY AT THE MOTOR CARRIER'S PRINCIPAL PLACE OF BUSINESS, OR WHERE THE VEHICLE IS HOUSED FOR 12 MONTHS FROM THE DATE OF THE INSPECTION. FOR QUESTIONS OR TO DISPUTE INFORMATION REGARDING THIS INSPECTION PLEASE USE THE FOLLOWING WEBSITE: [HTTPS://DATAQS.FMCSA.DOT.GOV](https://DATAQS.FMCSA.DOT.GOV)

Signature Of Motor Carrier Official X: \_\_\_\_\_

Date: \_\_\_\_\_

Report Prepared By:  
J. St. Laurent

Badge #:  
X805

Copy Received By:  
DUTHENE BAYARD

Page 2 of 2



3119062 WA WAX805006402

X \_\_\_\_\_

X \_\_\_\_\_



## DRIVER/VEHICLE EXAMINATION REPORT



Washington State Patrol  
SPOKANE POE  
PO Box 42614  
Olympia, WA 98504-2614  
Phone: (360) 596-3815  
Email/Web: www.wsp.wa.gov

Report Number: WAX805006402  
Inspection Date: 08/28/2024  
Start: 05:17 PM PDT End: 06:08 PM PDT  
Inspection Level: I  
HM Inspection Type: None

## MOTOR CARRIER INFORMATION

RIKI TRANSPORTATION INC  
8225 LECLAIRE AVE  
BURBANK, IL, 60459  
dba: BRZ  
USDOT#: 3119062  
MC/MX#:  
State#:  
Phone#: 7083035150  
Fax#:

Driver: Bayard, Duthene  
License# B630160762441  
State# FL  
Date of Birth# 07/04/1976

CoDriver:  
License#  
State#  
Date of Birth#

Location: Spokane Port of Entry  
MilePost: 298  
Highway: I-90 WB  
County: Spokane  
Shipper: Pella Corporation  
Bill of Lading: None  
Origin: MINNEAPOLIS, MN, US  
Destination: PORTLAND, OR, US  
Cargo: Plastic Articles

## STATE INFORMATION

State Page: SPECIAL PROJECT: BK24; DISTRICT (WSP ONLY): 04; DETACHMENT (WSP ONLY): 30; DATA Q / CHANGE: N; PORTAL CHECK: Y

Report Prepared By:  
J. St. Laurent

Badge #:  
X805

Copy Received By:  
DUTHENE BAYARD

Page 1 of 1



3119062 WA WAX805006402

X \_\_\_\_\_ X \_\_\_\_\_