

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 3 0 0 17

OHIO STATE HIGHWAY PATROL
MOTOR CARRIER ENFORCEMENT
DISTRICT 3 CLEVELAND
TELEPHONE (330)433-6210
FAX (614) 752-9274

Report Number: OH1338000162
Inspection Date: 08/26/2024
Start: 02:04 AM ET End: 2:33:31 AM ET
Inspection Level: III - Driver Only
HM Inspection Type: None

ZIGI FREIGHT INC
6850 W 63RD STREET
CHICAGO, IL 60638
USDOT#: 02828543
MC/MX#: 944686
State#:

Phone#: (630)485-7370
Fax#:

Driver: SANTOS JIMENEZ, ERICK A
License#: S0490 23261 02802
Date of Birth: 02/25/1980
CoDriver:
License#:
Date of Birth:

State: NJ

State:

Location: INTERSTATE 71 MILE POST 196
Highway: IR71
County: WAYNE, OH

MilePost: 196
Origin: TEMPE, AZ
Destination: BRISTOL, PA

Shipper: REFRESCO BEVERAGES US INC
Bill of Lading: 85415152
Cargo: BEVERAGES

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	P1150995	751	3AKJHHR6PSNM3962	52,500			
2	ST	GDAN	2022	ME	234236H	W97973	1GR1P0624NK334672	68,000			

BRAKE ADJUSTMENTS No Brake Measurements Required For Level 3

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392 2-ML	392 2	D	N	0209 (Last 4 #)	N	N	Failure to Maintain Lane: Driver was observed by Trooper Cornwell traveling out of his lane by over two tire widths.
392 2-INAT	392 2	D	N	0209 (Last 4 #)	N	N	Inattentive Driving: Driver stated to Trooper Cornwell that he drove out of his lane because he was eating food and looking at his gps
395 24C2III	395 24(c)(2)(iii)	D	N		N	N	Driver failed to manually add shipping document number. The shipping document number entered into the drivers log does not match the BOL number on the bill of lading. Photos were taken and the ERODS file has been saved

HazMat: No HM Transported

Placard: No **Cargo Tank:**

Special Checks: Traffic Enforcement

State Information:

FMCSA Credentials Verified(Y/N): Y, CDL Verified(Y/N): Y, FMCSA OOS Order Issued(Y/N): N, For-Hire Carrier: Y, Reason Code: TRAF, Driver Address Verified(Y/N): Y, Driver Address: 150 SYLVAN AVE APT 202, Driver City: NEWARK, Driver State: NJ, Driver Zip: 07104, Photos Taken(Y/N): Y,

Report Prepared By:
TPR K.R. PESHEK

Badge #
1338

Copy Received By:
ERICK SANTOS JIMENEZ

Page 1 of 2

X *Erick A. Santos*



02828543 OH OH1338000162

DRIVER/VEHICLE EXAMINATION REPORT

OHIO STATE HIGHWAY PATROL
MOTOR CARRIER ENFORCEMENT
DISTRICT 3 CLEVELAND
TELEPHONE (330)433-6210
FAX (614) 752-9274

Report Number: OH1338000162
Inspection Date: 08/26/2024
Start: 02:04 AM ET End: 2:33:31 AM ET
Inspection Level: III - Driver Only
HM Inspection Type: None

ZIGI FREIGHT INC
6850 W 63RD STREET
CHICAGO, IL 60638

USDOT#: 02828543
MC/MX#: 944686
State#:

Phone#: (630)485-7370
Fax#:

Location: INTERSTATE 71 MILE POST 196
Highway: IR71
County: WAYNE, OH

MilePost: 196
Origin: TEMPE, AZ
Destination: BRISTOL, PA

Driver: SANTOS JIMENEZ, ERICK A
License#: S0490 23261 02802
Date of Birth: 02/25/1980
CoDriver:
License#:
Date of Birth:

State: NJ

State:

Shipper: REFRESCO BEVERAGES US INC
Bill of Lading: 85415152
Cargo: BEVERAGES

ATTENTION DRIVER: This report must be sent to the motor carrier whose name appears at the top of this inspection report within 24 hours. If the inspection report cannot be delivered within 24 hours the driver must mail or fax the inspection report to the motor carrier.

***** POSSIBLE CDL DISQUALIFICATION *****

If this roadside inspection identified an alleged violation of one or more of the below noted regulations, your CDL may be disqualified. If the PUCO finds you committed a violation of any of these regulations, the violation will be treated as a conviction for the purposes of federal and state law and notice of such conviction will be forwarded to the Ohio Bureau of Motor Vehicles (BMV). The BMV may disqualify you from operating a commercial motor vehicle for a minimum of 60 days. Any BMV sanction is in addition to sanctions imposed by the Public Utilities Commission of Ohio (PUCO)

177.804(b)(1), 177.804(b)(2), 177.804(b)(3), 177.804(c), 4901.2-5-07D, 383.23(a)(2), 383.51(a), 383.51A-NSIN, 383.51A-NSOUT, 383.51A-SIN, 383.51A-SOUT, 383.91(a), 383.93(b)(1), 383.93(b)(2), 383.93(b)(3), 383.93(b)(4), 383.93(b)(5), 391.15(a), 391.15A-NSIN, 391.15A-NSOUT, 391.15A-SIN, 391.15A-SOUT, 392.10(a)(1), 392.10(a)(2), 392.10(a)(3), 392.10(a)(4), 392.11, 392.12, 392.4(a), 392.5(a)(2), 392.5A2-UI, 392.5(c)(2), 392.80(a), 392.82(a)(1), 395.13(d), 396.9(c)(2).

MOTOR CARRIER CERTIFICATION OF COMPLETED REPAIRS: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with the Federal Motor Carrier Safety & Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. A false certification of repairs is required to be prosecuted with penalties up to \$10,000.

Signature Of Repairer X: _____ Facility: _____ Date: _____

All violations of the FHMR and FMCSR or Title 49 of the Ohio Revised Code will be reviewed by the PUCO's Transportation Department to determine whether civil forfeitures should be assessed against any responsible parties in accordance with the penalty provisions of Title 49 of the Ohio Revised Code. If civil forfeitures are assessed, you will receive a separate notice by mail. These penalties may be assessed to motor carriers, shippers, and/or drivers.

ATTENTION MOTOR CARRIER: The motor carrier must examine this report and repair all the vehicle defects/violations noted above -AND- The motor carrier must sign the Certification of Repairs below and return the signed form to: Public Utilities Commission of Ohio, TASD - 4th floor, 180 E Broad St, Columbus, OH 43215-3793 -OR- Fax (614) 752-9274 within 15 days of the inspection. If "No Violations Were Discovered" then you do not need to return this report. Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000. If you have any questions, please contact (614) 466-0429.

Signature Of Motor Carrier X: _____ Title: _____ Date: _____

