

*****NOTICE*****

If this box is checked, a separate traffic citation was issued to the violator. Please refer to the issued traffic citation for additional information. This is in addition to any action required by this report.

NOTICE TO CARRIER: PLEASE SIGN THE CERTIFICATION BELOW AND RETURN THIS REPORT TO NEW MEXICO STATE POLICE COMMERCIAL VEHICLE ENFORCEMENT WITHIN FIFTEEN (15) DAYS. IF NO VIOLATIONS ARE NOTED ON THIS REPORT, DO NOT RETURN THE REPORT TO NMSP/CVE. PLEASE RETAIN IT FOR YOUR FILES.

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with NMSA 1978 65-3.1 through 65-3.13, and the New Mexico Carrier Safety Regulations.

New Mexico Department Of Public Safety

Commercial Vehicle Enforcement

P.O. Box 1628

Santa Fe, NM 87504-1628

Fax: (505) 827-9279

Report Prepared By:

TIW, MAYFIELD,

346230

I certify that the out of service violations listed in the "Violation Information" section have been satisfactorily repaired as of the date indicated.

Failure to return this report with the required certification can result in penalties up to \$1,000.00 per day for each day the violation continues, up to a total of \$10,000.

Driver
X

Carrier
X



**NEW MEXICO DEPARTMENT OF PUBLIC SAFETY****COMMERCIAL VEHICLE ENFORCEMENT**

P.O. BOX 1628

SANTA FE, NM 87504-1628

Phone: (505) 827-9277

Fax: (505) 827-9279

cveinspection.certi@state.nm.us

DRIVER / VEHICLE EXAMINATION REPORT

INSPECTION NUMBER NM6230091CFS	
Inspection Date: 11/20/2024	Time Zone: MT
Time Started: 10:10 AM	Time Ended: 10:40 AM
Inspection Level: Level 3: Driver-Only Inspection	

INSPECTION SUMMARY				
Location Description RATON PORT OF ENTRY		Highway 125	Milepost 460	County COLFAX
USDOT Number 02828543	MC Number	State Number	Facility Type F	
Carrier Name ZIGI FREIGHT INC		Carrier Phone (630) 485-7370	Interstate Commerce? ☒ Yes ☐ No	
Carrier Address 6850 W 63RD STREET		Carrier City CHICAGO	State IL	Zip Code 60638
Shipper ROBERT EMS		Cargo General Freight - 10	Bill of Lading 2258022997	International Load? ☐ Yes ☐ No
Origin City WEST LINN		Origin State OR	Destination City BATON ROUGE	Dest State LA
Cargo Seal Removed: No	Cargo Seal Replaced: No	Inspection Location Latitude 36.990829		Inspection Location Longitude -104.48356
☐ Border Enforcement Grant Funded ☐ Domestic Commerce ☐ Foreign Commerce				

Special Checks

- | | | | |
|---|--|--|--------------------------------------|
| ☐ Alcohol/Controlled Substance Check | ☐ Traffic Enforcement | ☐ Size and Weight Enforcement | ☐ Drug Arrest |
| ☐ Conducted by Local Jurisdiction | ☐ Post Crash Inspection | ☐ E-Screening | ☐ Re-Inspect |
| ☐ Drug Interdiction Search | ☐ PASA Conducted Inspection | ☐ PBBT Inspection | |

DRIVER / CO-DRIVER INFORMATION						
Driver Status DRIVER	Last Name SOLANO	First Name CARLOS	Middle Name	DOB 06/14/1977	License Number S450100772140	State FL

VEHICLE INFORMATION												
Unit	Type	Year	Make	State	License #	Equipment ID	Unit VIN	GVWR	CVSA #	Status	CVSA Issued #	OOS Str #
1	TT	2022	FRHT	IL	P1150974	unit 730	3AKJHFG9NSNM3995	52,000				
Cargo Seal Removed ID:						Cargo Seal Replaced ID:						
2	ST	2022	GDA	ME	452000Z	unit 94948	1GR1P0621NJ324235	68,000				
Cargo Seal Removed ID:						Cargo Seal Replaced ID:						

HAZARDOUS MATERIAL INFORMATION						
HM Unit	HazMat Inspection Type	Cargo Tank Type	HM Code	Reportable Quantity	Placards Required	HM Waste
1	0-None					

VIOLATION INFORMATION									
Violation	Violation Unit	Violation Code	Violation Section	Violation Date	OOS	OOS Verified	Post Crash	Citation Type	Citation Num
1									

Violation Description:									
------------------------	--	--	--	--	--	--	--	--	--

VIOLATION INFORMATION									
------------------------------	--	--	--	--	--	--	--	--	--

No Violations Reported