

8/6/24, 11:10 AM

FMCSA - Inspection Platform

DRIVER/VEHICLE EXAMINATION REPORT



Idaho State Police
Commercial Vehicle Safety
700 S Stratford Dr
Meridian, ID 83642-6202
Phone: (208) 884-7220 Fax: (208) 884-7192
Email/Web: cvsmail@isp.idaho.gov

Report Number: ID3640005131
Inspection Date: 08/06/2024
Start: 10:54 AM MDT End: 11:15 AM MDT
Inspection Level: III
HM Inspection Type: None

RIKI TRANSPORTATION INC

8225 LECLAIRE AVE

BURBANK, IL, 60459

dba: BRZ

USDOT#: 3119062

MC/MX#:

State#:

Phone#: 7083035150

Fax#:

Driver: Canga Romero, Cinley

License#: C526280802210

State# FL

Date of Birth#: 06/21/1980

CoDriver:

License#

State#

Date of Birth#

Location: Caldwell ID

MilePost:

Highway: Vietnam Veterans Memorial Highway

County: Canyon County

Shipper: Credit Tire, Indiana

Bill of Lading: 56024

Origin: ELKHART, IN, US

Destination: BOARDMAN, OR, US

Cargo: General Freight

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	PI153327	606	3AKJHHD99PSUA1584	52,000				
2	ST	CDAN	2022	ME	451976Z	W94924	1CR1P0629NJ324211	68,000				

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Vio Code	Section	Unit	OOS	Citation #	Verify	Violations Discovered
392.2-SLLSWZ	392.2	D	N		N	State/Local Laws - Speeding work/construction zone: IC 49-657 Speeding 63 in 55 mph Work Zone

Special Checks:

No Data for Special Checks.

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. (49 CFR 396.9(c)(1))

Signature Of Motor Carrier Official X: [Signature] Date: 12/13/24Report Prepared By:
Jerry LawBadge #:
3640Copy Received By:
CINLEY CANCA ROMERO

Page 1 of 1

X

X



3119062 ID: ID3640005131

https://report.fmcsmail.idaho.gov/#inspection/confirm