FMCSA - Inspection Platform

DRIVER/VEHICLE EXAMINATION REPORT



South Dakota Highway Patrol District 4 Zone 3 118 West Capitol Ave Pierre, SD 57501

Phone: 605-224-7364 Fax: 605-773-7144 Email/Web: website: sdtruckinfo.sd.gov Report Number: SD5620001677 Inspection Date: 10/06/2024

Start: 08:04 AM CDI End: 08:23 AM CDT

Inspection Level III HM Inspection Type: None

RIKITRANSPORTATION INC 8225 LECLAIRE AVE

BURBANK, IL, 60459 dba: BRZ

USDOT#: 3119062 MC/MX#: State#:

Phone#: 7083035150

Fax#:

Driver: Rodriguez, Rene License# R362720731250

State# FL

Date of Birth# 04/05/1973

CoDriver: License# State# Date of Birth# -Location: Jefferson Scale NB

MilePost: 13 Highway: I-29 NB County: Union

Cargo: Beverages

Shipper: BERRY GLOBAL, INC Bill of Lading: 08202733 Origin: HATTIESBURG, MS, US Destination: BUTTE, MT, US

VEHICLE IDENTIFICATION

Unit	Туре	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA#	CVSA Issued #	OOS Sticker
1	П	MACK	2020	IL	P1151472	822	1M1AN4GY4LM017941	52,000				
2	ST	GDAN	2022	ME	454508Z	WG7040	1GR1P0626ND335049	68,000			1. 1.1.1	

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

No Violations Were Discovered.

Checks:

E-Screen

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. [49 CFR 396.9(d)[1]]

Date: Signature Of Motor Carrier Official X:

JEFF PETERSON

Badge #:

Copy Received By: RENE RODRIGUEZ age 1 of 1



3119062 SD SD5620001677

https://safespect.fmcsa.dot.gov/#/inspection/confirm

Scanned with CS CamScanner

1/1