



California Highway Patrol
32829 Interstate 5
Lebec, CA 93243
Phone: (661) 858-2540

Report Number: CANEZA001460
Inspection Date: 12/11/2024
Start: 3:06 AM PT End: 3:34 AM PT
Inspection Level: I - Full
HM Inspection Type: None

Carrier: ZIGI FREIGHT INC. Internationally Accredited Agency CHP407F/343A

DBA: ROYAL3 INC
6850 W 63RD STREET
CHICAGO, IL, 60638

USDOT: 2828543 Phone#: (630)485-7370
MC/MX#: 944686 Fax#: (630)485-6980
State#:

Location: GRAPEVINE IF

Highway: I-5

County: KERN

Email: ZIGI@ROYAL3INC.COM

Driver: ASSENZA, DARRIN C

License#: A252163673320

State: FL

Date of Birth: 09/12/1967

CoDriver:

License#:

State:

Date of Birth:

Milepost: Shipper: BEST LOGISTICS

Origin: STOCKTON, CA

Bill of Lading: 24168159

Destination: MONTEBELLO, CA

Cargo: GENERAL FREIGHT

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GWR	CVSA Existing	CVSA #
1	TT	FRHT	2021	IL	P1095152	722	3AKJHHDR4MSMZ5504	52000		
2	ST	GDAN	2018	TN	U769071	289471	1GRAP0621JT106133	68000		

BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	1 1/4	1 1/4	1 1/4	2	1
Left	1 1/4	1 1/4	1 1/4	INOP	1
Chamber	L-24*	L-30	L-30	C-30	C-30

VIOLATIONS

Section	Type	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
393.48A-BIBD	F	2	N	WARNING	N	N	Drum Brake - Inoperative other than a steering axle: V2- X4 L/S INOPERATIVE BRAKE CLEVIS IS NOT CONNECTED TO BRAKE CHAMBER PUSH ROD
34620(a) CVC	S	1	N	WARNING	N	N	Intrastate motor carrier of property is operating without an active motor carrier of property (MCPP) permit-392.2AU-Specify: CALIFORNIA LOAD TRAVELING FROM STOCKTON, CA TO MONTEBELLO, CA MOTOR CARRIER PERMIT IS REQUIRED. PLEASE CALL (916) 657-8153

HazMat: No HM transported

Placard:

Cargo Tank:

Special Checks: Alcohol/Controlled Substance Check
Conducted by Local Jurisdiction
X Size and Weight Enforcement
X eScreen Inspection

Traffic Enforcement
PASA Conducted Inspection
Drug Interdiction Search

Post Crash Inspection
PBBT Inspection

State Information:

Beat/Sub Area: 890; Regulated Vehicle: Y; Pre-Cleared Vehicle: Y; Veh #1 Type: 25; Veh #2 Type: 40; Officer ID1: 17884;
Cit-1: WARNING; Cit-2: WARNING

Notes: V1-3X GREEN TT V2- 2X WHT VAN

V1-34482843

Pursuant to Section 24004 CVC, violations recorded on this SafetyNet Inspection Report must be corrected prior to redispach. Violations marked out of service must be corrected before the vehicle is operated on the highway. For your convenience, KEEP THIS REPORT OR A COPY IN THE VEHICLE UNTIL ALL VIOLATIONS ARE CLEARED. This document should NOT be forwarded to the court for clearance procedures. DO NOT RETURN THIS FORM TO THE CALIFORNIA HIGHWAY PATROL.



TRUCKERS AGAINST TRAFFICKING

If you suspect human trafficking please contact 911 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainstrafficking.org/> to learn more.





California Highway Patrol

32829 Interstate 5

Lebec, CA 93243

Phone: (661) 858-2540

Internationally Accredited Agency CHP407F/343A

Report Number: CANEZA001460

Inspection Date: 12/11/2024

Start: 3:06 AM PT End: 3:34 AM PT

Inspection Level: I - Full

HM Inspection Type: None

Report Prepared By:

O. Gonzalez

Unit #:

424

ID/Badge #:

A19414

Copy Received By:

DARRIN ASSENZA

XX