DRIVER/VEHICLE EXAMINATION REPORT

A PO Box Helena Dhone	Montana Department of Transportation MCS District 3 PO Box 4539 Helena, MT 59504 Phone: 406-444-3300 Fax 406-444-7551 Email/Web: mdtmcssafet/@mt.gov				Report Number: MTU529700585 Inspection Date: 01/16/2025 Start: 10:15 AM MST End: TLOS AM MST Inspection Level: II HM Inspection Type: None	
RIKI TRANSPORTATION INC 8225 LECLAIRE AVE BURBANK, IL, 60459 dbat BRZ USDOT#: 3119062 Mc/MX#: State#: Phone#: 7083035150 Fax#:			Driver: White, Dwight, Lashun License# 09737462 State# TX Date of Birth# 07/11/1970		Location: Armington Junction Weigh Station MilePost: Highway: US 87 / US 89 County: CASCADE	
			CoDriver: License# State#		Shipper: agrigro marketing Bill of Lading: Origin: DONIPHAN, MO, US Destination: ULM, MT, US	
			Date of Birth#		Cargo: agricultural chemicals	
VEHICLE IDENTIFIC Unit Type Make 1 TT MACK	Vear State Plat 2023 IL P954	547	a the second sec			
VEHICLE IDENTIFIC Unit Type Make 1 TT MACK 2 ST WANC Unit 1	Vear State Plat 2023 IL P954 2017 ME 4048 Carr	547 123Z go Seal R 0064	11/1A/4 1337/52 temoved # 48	4GY3PMO		
VEHICLE IDENTIFIC Unit Type Make 1 TT MACK 2 ST WANC Unit 1 VIOLATIONS ATTRI	Vear State Plat 2023 IL P954 2017 ME 4048 Cary BUTABLE TO TH	547 523Z go Seal R 0064 HE MOTO	IMIAN 133V53 temoved # 48 DR CARRIER	4GY3PM0 32D8HL02	31934 52,000 8378 68,000 Cargo Seal Replaced # MCS 00010030	
VEHICLE IDENTIFIC Unit Type Make 1 TT MACK 2 ST WANC	Vear State Plat 2023 IL P954 2017 ME 4048 Carr	547 523Z go Seal R 0064 HE MOTO	11/1A/4 1337/52 temoved # 48	4GY3PM0 32D8HL02	31934 52,000 8378 68,000 Cargo Seal Replaced #	
VEHICLE IDENTIFIC Unit Type Make 1 TT MACK 2 ST WANC Unit 1 VIOLATIONS ATTRI Vio Code	Year State Plat 2023 IL P354 2017 ME 4048 Carr BUTABLE TO TH Section	547 323Z go Seal R 0064 HE MOTO Unit	IMIAN 133753 temoved # 48 DR CARRIER 005 Citation #	4C Y3PMG I2D8HL02I Verify	31934 52,000 8378 68,000 Cargo Seal Replaced # MCS 00010030 Violations Discovered Cargo - Immobilized, such so that it cannot shift or tip to the extent that the vehicle's stability or maneuverability is adversely affected: Loads of totes shifted all the way to the passenger side of the trailer causing the trailer to lean. trailer not currently in contact with	

Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. ALL MECHANICAL VIOLATIONS MUST BE REPAIRED PRIOR TO THE VEHICLE BEING REDISPATCHED.

Signature Of Repairer X:	Facility:	Date:
NOTE TO DRIVER This report must be furnished to the mot NOTE TO MOTOR CARRIERS. This certification MUST BE SIC	tor carrier whose name appears at the top of INED by the Motor Carrier and RETURNED W	this report. (THIN 15 days (only when violations have been
noted) to the email address, fax number, or address indicat		

12 months from the date of the inspection. Signature Of Motor Carrier Official X:

Date:

Other Driver / Carrier Notifications

TRUCKERS AGAINST TRAFFICKING ---- If you suspect human trafficking, please contact 9-1-1 for emergencies. For tips and information contact the Montana 24-hour hotline at 1-833-406-STOP or the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Co to 406STOP.com or truckersagainsttrafficking org to learn more.

J Buckley Badge #: U5297

Copy Received By: DWIGHT LASHUN WHITE

X

Page 1 of 1

