



NEW MEXICO DEPARTMENT OF PUBLIC SAFETY COMMERCIAL VEHICLE ENFORCEMENT

P.O. BOX 1628
SANTA FE, NM 87504-1628

Phone: (505) 827-9277
Fax: (505) 827-9279

cveinspection.certi@state.nm.us

DRIVER / VEHICLE EXAMINATION REPORT

INSPECTION NUMBER NM9520P0EC4C	
Inspection Date: 1/14/2025	Time Zone: MT
Time Started: 9:51 AM	Time Ended: 10:16 AM
Inspection Level: Level 3: Driver-Only Inspection	

INSPECTION SUMMARY			
Location Description GALLUP PORT OF ENTRY	Highway I40	Milepost 12	County MCKINLEY
USDOT Number 2828543	MC Number	State Number	Facility Type F
Carrier Name ROYAL3 INC	Carrier Phone (630) 485-7370	Interstate Commerce? ☒ Yes ☐ No	
Carrier Address 6850 W 63RD STREET	Carrier City CHICAGO	State IL	Zip Code 60638
Shipper BENT RIVER MACHINE	Cargo MACHINERY	Bill of Lading 2756112	International Load? ☐ Yes ☐ No
Origin City CLARKDALE	Origin State AZ	Destination City SPRINGFIELD	Dest State VA
Cargo Seal Removed:	Cargo Seal Replaced:	Inspection Location Latitude 35.487051	Inspection Location Longitude -108.90248
☐ Border Enforcement Grant Funded ☐ Domestic Commerce ☐ Foreign Commerce			

Special Checks

- | | | | |
|---|--|--|--------------------------------------|
| ☐ Alcohol/Controlled Substance Check | ☐ Traffic Enforcement | ☐ Size and Weight Enforcement | ☐ Drug Arrest |
| ☐ Conducted by Local Jurisdiction | ☐ Post Crash Inspection | ☒ E-Screening | ☐ Re-Inspect |
| ☐ Drug Interdiction Search | ☐ PASA Conducted Inspection | ☐ PBBT Inspection | |

DRIVER / CO-DRIVER INFORMATION												
Driver Status DRIVER	Last Name VENTURA	First Name NELSON	Middle Name B	DOB 08/01/1974	License Number V536622742810	State FL						
VEHICLE INFORMATION												
Unit	Type	Year	Make	State	License #	Equipment ID	Unit VIN	GVWR	CVSA #	Status	CVSA Issued #	OOS Strk #
1	TT	2021	FRHT	IL	P1095158	unit-728	3AKJHHDRXMSMZ5510	52,500				
Cargo Seal Removed ID:						Cargo Seal Replaced ID:						
2	ST	2024	HYT	TN	450399T	unit-2244736	3H3V532K5RS119291	68,000				
Cargo Seal Removed ID:						Cargo Seal Replaced ID:						
HAZARDOUS MATERIAL INFORMATION												
HM Unit	HazMat Inspection Type	Cargo Tank Type	HM Code	Reportable Quantity	Placards Required	HM Waste						
1	0-None											
VIOLATION INFORMATION												
Violation	Violation Unit	Violation Code	Violation Section	Violation Date	OOS	OOS Verified	Post Crash	Citation Type	Citation Num			
1												
Violation Description:												

VIOLATION INFORMATION

No Violations Reported