

DRIVER/VEHICLE EXAMINATION REPORT

RIMS 1.7.3



Kentucky State Police
Commercial Vehicle Enforcement Division
 919 Versailles Road
 Frankfort, Kentucky 40601
 cveinspections@ky.gov

Report Number: KYCV41756153
Inspection Date: 02/05/2024
Start: 06:14 AM ET **End:** 06:57 AM ET
Inspection Level: I - Full
HM Inspection Type: None

RIKI TRANSPORTATION INC
 8225 LECLAIRE AVE
 BURBANK, IL, 60459
USDOT: 3119062
MC/MX#: 86875
State#:

Phone#: (708) 303-5150
Fax#:

Driver: FAJARDO, JOSE
License#: F263421683750 **State:** FL
Date of Birth: 10/15/1968
CoDriver:
License#: **State:**
Date of Birth:

Location: MOREHEAD
Highway: I-64 WB WS
County: ROWAN

Milepost: 149
Origin: WINCHESTER, VA
Destination: WINCHESTER, KY

Shipper: CROWN CORK
Bill of Lading: 30049815
Cargo: GENERAL FREIGHT

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA #	Issued #	OOS Sticker
1	TT	MACK	2020	IL	P1151474	824	1M1AN4GY4LM017938	53200		33720709	
2	ST	GDAN	2018	TN	U769073	289743	1GRAP0625JT106135	68000			

BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	N/A	N/A	N/A	1 1/4	1 1/2
Left	N/A	N/A	N/A	1 1/4	1 1/2
Chamber	DISC	DISC	DISC	C-30	C-30

VIOLATIONS: No violations were discovered

HazMat: No HM transported

Special Checks:

Alcohol/Controlled Substance Check	Traffic Enforcement	Post Crash Inspection
Conducted by Local Jurisdiction	PASA Conducted Inspection	PBBT Inspection
Size and Weight Enforcement	Drug Interdiction Search	
X eScreen Inspection	Border Enforcement Inspection	

State Information: Driver's Lic. Check (Y or N): Y; Carrier Verification (Y or N): Y

Attention Motor Carrier: If the inspection indicates NO violations/defects on the driver and or vehicle no copy of the inspection needs to be returned to the investigating agency. The carrier should maintain a copy of the inspection pursuant to retention guidelines.

[Signature]

Safety manager
 02/07/24.

Report Prepared By: **Badge #:**
 L. HOLBROOK 4175

Radio #:
 4175

Copy Received By:
 JOSE FAJARDO

X



03119062 KY KYCV41756153