

## DRIVER/VEHICLE EXAMINATION REPORT



Arizona Department of Public Safety  
1640's  
PO Box 18410  
Phoenix, AZ 85005  
Phone: 520-260-4865  
Email/Web: returndver@azdps.gov

Report Number: AZ6847001068  
Inspection Date: 02/21/2025  
Start: 08:00 AM MST End: 09:00 AM MST  
Inspection Level: II Certification Date:  
HM Inspection Type: None

ZIGI FREIGHT INC  
6850 W 63RD STREET  
CHICAGO, IL, 60638  
dba: ROYAL3 INC  
USDOT#: 2828543  
MC/MX#:  
State#:  
Phone#: 6304857370  
Fax#: 6304856980

Driver: Henry, Lerone, Andre  
License# H560521862081  
State# FL  
Date of Birth# 06/08/1986  
CoDriver:  
License#  
State#  
Date of Birth#

Location: BENSON AZ  
MilePost: 312  
Highway: I-10  
County: COCHISE  
Shipper: EMSON  
Bill of Lading: 3500365  
Origin: MIRA LOMA, CA, US  
Destination: MIAMI, FL, US  
Cargo: General Freight

## VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	P1056937	757	3AK0HHDR2PSNM3957	52,500				
2	ST	GDAN	2022	ME	451981Z	W94929	1GRIP0628N3324216	68,000				

## VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Vio Code	Section	Unit	OOS	Citation #	Verify	Violations Discovered
392.2-SLLMF	392.2	2	N		U	State/Local Laws - Wheel (mud) flaps missing or defective: PASSENGER SIDE MUDFLAP DAMAGED AND PULLED UP INTO TIRES AND MOUNT IS BENT SO THAT IT IS ALMOST TOUCHING THE OUTSIDE TIRE.
393.75A3-TAOL	393.75(a)(3)	2	Y		U	Tires - All others, leaking or inflation less than 50% of the maximum inflation pressure on tire not equipped with ATIS: #5 AXLE PASSENGER SIDE INSIDE TIRE IS FLAT AND JUST THE SIDEWALLS ARE LEFT.

## Special Checks:

Other

\* Pursuant to the authority contained in ARS 28-5204, I hereby declare vehicles with defects followed by a "Y" in the OOS column of the Violations section of this report to be OUT OF SERVICE. No person shall remove the Out of Service stickers applied to these vehicles, or operate such vehicles until the Out of Service defects have been repaired and the vehicles have been restored to safe operating conditions. Driver's initials: *XLA*

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. False certifications of the required repairs are required to be prosecuted with penalties up to \$10,000.

Signature Of Repairer X:

*Michael W. Pace*

Facility: *LEWIS #460*Date: *2/21/25*

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report, if there are no vehicle violations on this inspection, it does not need to be signed and returned to the inspecting state. Keep the inspection on file at the business.

NOTE TO MOTOR CARRIERS: DRIVER & MOTOR CARRIER: This report must be furnished to the above named motor carrier. The motor carrier shall sign below and return, by mail or email, within 15 days to: Arizona Department of Public Safety Commercial Vehicle Enforcement Bureau PO Box 18410 Phoenix, Arizona 85005-8410 Email: returndver@azdps.gov The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Material Regulations as adopted by Arizona Revised Statutes 28-5204 insofar as they are applicable to motor carriers and drivers. Violations, other than OOS conditions, detected during the inspection process will not preclude the completion of the current trip or dispatch. However, such violations must be corrected or repaired prior to re-dispatch.

Signature Of Motor Carrier Official X:

Date: *02/21/25*

Report Prepared By:  
Tpr Troy McCall

Badge #: 6847  
Radio #: 6847

Copy Received By:  
LERONE ANDRE HENRY

Page 1 of 2



2828543 AZ AZ6847001068

# DRIVER/VEHICLE EXAMINATION REPORT



Arizona Department of Public Safety  
1640's  
PO Box 18410  
Phoenix, AZ 85005  
Phone: 520-260-4865  
Email/Web: returndver@azdps.gov

Report Number: AZ6847001068  
Inspection Date: 02/21/2025  
Start: 08:00 AM MST End: 09:00 AM MST  
Inspection Level: II Certification Date:  
HM Inspection Type: None

ZIGI FREIGHT INC  
6850 W 63RD STREET  
CHICAGO, IL, 60638  
dba: ROYAL3 INC  
USDOT#: 2828543  
MC/MX#:  
State#:  
Phone#: 6304857370  
Fax#: 6304856980

Driver: Henry, Lerone, Andre  
License# H560521862081  
State# FL  
Date of Birth# 06/08/1986  
CoDriver:  
License#  
State#  
Date of Birth#

Location: BENSON AZ  
MilePost: 312  
Highway: I-10  
County: COCHISE  
Shipper: EMSON  
Bill of Lading: 3500365  
Origin: MIRA LOMA, CA, US  
Destination: MIAMI, FL, US  
Cargo: General Freight

## Other Driver / Carrier Notifications



TRUCKERS AGAINST TRAFFICKING --- If you suspect human trafficking, please contact 9-1-1 and call the National Human Trafficking Hotline at 1-888-373-7888. Make the call, save lives! Go to <https://truckersagainsttrafficking.org/> to learn more.

Report Prepared By:  
Tpr Troy McCall

Badge #: Radio #:  
6847 6847

Copy Received By:  
LERONE ANDRE HENRY

Page 2 of 2



2828543 AZ AZ6847001068

X



Truck  
757

# TOTAL TRUCK CARE

LOVE'S  
0460 Benson, AZ TRUCKCARE  
643 State Road 90 Benson, AZ 85602  
(520) 586-8702

WORK ORDER #: 4006064402  
WORK ORDER DATE: 02/21/2025  
CLOSE DATE:  
SERVICE TYPE: Roadside

SHIP TO: England Carrier Services(3408710)  
PO BOX 27566  
Salt Lake City, UT 84127-0566  
(800) 848-7810

SOLD TO: England Carrier Services(34087  
PO BOX 27566  
Salt Lake City, UT 84127-0566

BILL TO: ENGLAND LOGISTICS/EC SERVICES(  
1325 S 4700 W  
Tooele, UT 84074  
ACCOUNT #: 20037505

<input type="checkbox"/> TRACTOR # 757	VIN #	YEAR	MAKE	MILEAGE	PLATE#/STATE	ENGINE
<input checked="" type="checkbox"/> TRAILER # W94929	VIN #	YEAR	MAKE	HUBOMETER	PLATE#/STATE	REEFER #
APU# / HOURS	ADDITIONAL UNIT	START TIME	END TIME	DRIVER NAME Henry	DRIVER CONTACT 8134452185	
Authorization # 3000108195	AUTHORIZATION NAME SAMUEL OWUSU	PAY TYPE NAB Yokohama	PO#	PO ISSUED BY	DR# EG00129527	

COMPLAINT:  
My carrier Henry with BRZ/Royal 3 is needing a road service for 1 Yokohama 109L Bluearth trailer tire and a mud flap. Please give me a call if you have any questions  
801-656-4699.

DESCRIPTION	MECHANIC	UOM	QUANTITY	LIST PRICE	PRODUCT	LABOR	EXTENSION
Tire Replacement		EA	1.00	0.00	0.00	0.00	0.00
Y10901 295/75R22 5 BE 109L LRG		EA	1.00	0.00	0.00	0.00	0.00
FET							0.00
VALVE STEM STANDARD		EA	1.00	0.00	0.00	0.00	0.00
TIRE DISPOSAL		EA	1.00	0.00	0.00	0.00	0.00
ROADSIDE: TIRE HOURLY LABOR		EA	2.50	0.00	0.00	0.00	0.00
FUEL SURCHARGE		EA	1.00	0.00	0.00	0.00	0.00
MUD FLAP REPLACEMENT		EA	1.00	0.00	0.00	0.00	0.00
ASC 73757 NJKMFP24X30 LOVES MUD FLAP		EA	1.00	0.00	0.00	0.00	0.00
Unit: TRAILER	Old Brand:	Position: RRO	Failure Reason:	Old Tread Depth:	Old DOT#:	New DOT#:	
						Parts	0.00
						Labor	0.00
						Tires	0.00
						Fees	0.00
						Customer Discount*	0.00



## TOTAL TRUCK CARE

LOVE'S  
0460 Benson, AZ TRUCKCARE  
643 State Road 90 Benson, AZ 85602  
(520) 586-8702

WORK ORDER #: 4006064402  
WORK ORDER DATE: 02/21/2025  
CLOSE DATE:  
SERVICE TYPE: Roadside

SHIP TO: England Carrier Services(3408710)  
PO BOX 27566  
Salt Lake City, UT 84127-0566  
(800) 848-7810

SOLD TO: England Carrier Services(34087  
PO BOX 27566  
Salt Lake City, UT 84127-0566

BILL TO: ENGLAND LOGISTICS/EC SERVICES(  
1325 S 4700 W  
Tooele, UT 84074  
ACCOUNT #: 20037505

Site Discount	0.00
Tax	0.00
<b>Total</b>	<b>0.00</b>

\* Customer Discount may include coupons, MLR rewards, and applicable discounts

SERVICE COMMENTS:

Driver Signature:

Service Location: Texas Canyon Rest Area 1-10 East, Dragoon, AZ 85609

DID YOU LOVE IT?

Please take a short survey about your experience today:  
Visit [Loves.com/survey](https://Loves.com/survey)

Or Scan the QR Code below:

