

DRIVER/VEHICLE EXAMINATION REPORT



Arizona Department of Public Safety
1640's
PO Box 18410
Phoenix, AZ 85005
Phone: 520-260-4865
Email/Web: returndver@azdps.gov

Report Number: AZ6847001068
Inspection Date: 02/21/2025
Start: 08:00 AM MST End: 09:00 AM MST
Inspection Level: II Certification Date:
HM Inspection Type: None

ZIGI FREIGHT INC
6850 W 63RD STREET
CHICAGO, IL, 60638
dba: ROYAL3 INC
USDOT#: 2828543
MC/MX#:
State#:
Phone#: 6304857370
Fax#: 6304856980

Driver: Henry, Lerone, Andre
License# H560521862081
State# FL
Date of Birth# 06/08/1986
CoDriver:
License#
State#
Date of Birth#

Location: BENSON AZ
MilePost: 312
Highway: I-10
County: COCHISE
Shipper: EMSON
Bill of Lading: 3500365
Origin: MIRA LOMA, CA, US
Destination: MIAMI, FL, US
Cargo: General Freight

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2023	IL	P1056937	757	3AKJHHDR2PSNM3957	52,500				
2	ST	GDAN	2022	ME	451981Z	W94929	1GR1P0628NJ324216	68,000				

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

Vio Code	Section	Unit	OOS	Citation #	Verify	Violations Discovered
392.2-SLLMF	392.2	2	N		U	State/Local Laws - Wheel (mud) flaps missing or defective: PASSENGER SIDE MUDFLAP DAMAGED AND PULLED UP INTO TIRES AND MOUNT IS BENT SO THAT IT IS ALMOST TOUCHING THE OUTSIDE TIRE.
393.75A3-TAOL	393.75(a)(3)	2	Y		U	Tires - All others, leaking or inflation less than 50% of the maximum inflation pressure on tire not equipped with ATIS: #5 AXLE PASSENGER SIDE INSIDE TIRE IS FLAT AND JUST THE SIDEWALLS ARE LEFT.

Special Checks:

Other

* Pursuant to the authority contained in ARS 28-5204, I hereby declare vehicles with defects followed by a "Y" in the OOS column of the Violations section of this report to be OUT OF SERVICE. No person shall remove the Out of Service stickers applied to these vehicles, or operate such vehicles until the Out of Service defects have been repaired and the vehicles have been restored to safe operating conditions. Driver's initials: *SLH*

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. False certifications of the required repairs are required to be prosecuted with penalties up to \$10,000.

Signature Of Repairer X: *Michael W. Rice* Facility: *LOVES #460* Date: *2/21/25*

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. If there are no vehicle violations on this inspection, it does not need to be signed and returned to the inspecting state. Keep the inspection on file at the business.

NOTE TO MOTOR CARRIERS: DRIVER & MOTOR CARRIER: This report must be furnished to the above named motor carrier. The motor carrier shall sign below and return, by mail or email, within 15 days to: Arizona Department of Public Safety Commercial Vehicle Enforcement Bureau PO Box 18410 Phoenix, Arizona 85005-8410 Email: returndver@azdps.gov The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with the Federal Motor Carrier Safety and Hazardous Material Regulations as adopted by Arizona Revised Statutes 28-5204 insofar as they are applicable to motor carriers and drivers. Violations, other than OOS conditions, detected during the inspection process will not preclude the completion of the current trip or dispatch. However, such violations must be corrected or repaired prior to re-dispatch.

Signature Of Motor Carrier Official X: _____ Date: _____

Report Prepared By:
Tpr Troy McCall

Badge #: Radio #:
6847 6847

Copy Received By:
LERONE ANDRE HENRY

Page 1 of 2



2828543 AZ AZ6847001068