



NEW MEXICO DEPARTMENT OF PUBLIC SAFETY

COMMERCIAL VEHICLE ENFORCEMENT

P.O. BOX 1628

SANTA FE, NM 87504-1628

Phone: (505) 827-9277

Fax: (505) 827-9279

cveinspection.certi@state.nm.us

DRIVER / VEHICLE EXAMINATION REPORT

INSPECTION NUMBER NM2438P1S89L	
Inspection Date: 3/5/2025	Time Zone: MT
Time Started: 7:22 AM	Time Ended: 7:49 AM
Inspection Level: Level 2: Walk-Around Inspection	

INSPECTION SUMMARY			
Location Description RATON PORT OF ENTRY	Highway I25	Milepost 460	County COLFAX
USDOT Number 02828543	MC Number	State Number	Facility Type F
Carrier Name ZIGI FREIGHT INC	Carrier Phone (630) 485-7370	Interstate Commerce? ☒ Yes ☐ No	
Carrier Address 6850 W 63RD STREET	Carrier City CHICAGO	State IL	Zip Code 60638
Shipper RED HILL LAVA	Cargo General Freight - 10	Bill of Lading 44002598	International Load? ☐ Yes ☐ No
Origin City WALSENBURG	Origin State CO	Destination City RATON	Dest State NM
Cargo Seal Removed:	Cargo Seal Replaced:	Inspection Location Latitude 36.990829	Inspection Location Longitude -104.48356
☐ Border Enforcement Grant Funded ☐ Domestic Commerce ☐ Foreign Commerce			

Special Checks

- | | | | |
|---|--|--|--------------------------------------|
| ☐ Alcohol/Controlled Substance Check | ☐ Traffic Enforcement | ☐ Size and Weight Enforcement | ☐ Drug Arrest |
| ☐ Conducted by Local Jurisdiction | ☐ Post Crash Inspection | ☒ E-Screening | ☐ Re-Inspect |
| ☐ Drug Interdiction Search | ☐ PASA Conducted Inspection | ☐ PBBT Inspection | |

DRIVER / CO-DRIVER INFORMATION						
Driver Status DRIVER	Last Name CRUZ MARTIN	First Name FREDY	Middle Name	DOB 01/28/1973	License Number 40122715	State TX

VEHICLE INFORMATION												
Unit	Type	Year	Make	State	License #	Equipment ID	Unit VIN	GVWR	CVSA #	Status	CVSA Issued #	OOS Strk #
1	TT	2023	FRHT	IL	P1150984	unit 740	3AKJHHDR8PSNM3946	52,500				
Cargo Seal Removed ID:						Cargo Seal Replaced ID:						
2	ST	2023	WAN	IN	PB51478	unit 251826	1JJV532D6PL387176	68,000				
Cargo Seal Removed ID:						Cargo Seal Replaced ID:						

HAZARDOUS MATERIAL INFORMATION						
HM Unit	HazMat Inspection Type	Cargo Tank Type	HM Code	Reportable Quantity	Placards Required	HM Waste

VIOLATION INFORMATION									
Violation	Violation Unit	Violation Code	Violation Section	Violation Date	OOS	OOS Verified	Post Crash	Citation Type	Citation Num
1									
Violation Description:									

VIOLATION INFORMATION									
No Violations Reported									

*****NOTICE*****

☐ If this box is checked, a separate traffic citation was issued to the violator. Please refer to the issued traffic citation for additional information. This is in addition to any action required by this report.

NOTICE TO CARRIER: PLEASE SIGN THE CERTIFICATION BELOW AND RETURN THIS REPORT TO NEW MEXICO STATE POLICE: COMMERCIAL VEHICLE ENFORCEMENT WITHIN FIFTEEN (15) DAYS. IF NO VIOLATIONS ARE NOTED ON THIS REPORT, DO NOT RETURN THE REPORT TO NMSP/CVE. PLEASE RETAIN IT FOR YOUR FILES.

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with NMSA 1978 65-3-1 through 65-3-13, and the New Mexico Carrier Safety Regulations.

New Mexico Department Of Public Safety

Commercial Vehicle Enforcement

P.O. Box 1628

Santa Fe, NM 87504-1628

Fax: (505) 827-9279

Report Prepared By:

TI I. HORSTMAN,

342438

I certify that the out of service violations listed in the "Violation Information" section have been satisfactorily repaired as of the date indicated. Failure to return this report with the required certification can result in penalties up to \$1,000.00 per day for each day the violation continues, up to a total of \$10,000.

Driver
X

Fredy Cruz

Carrier
X

