

DRIVER/VEHICLE EXAMINATION REPORT



State of Ohio
Public Utilities Commission of Ohio
180 E Broad St
Columbus, OH 43215
Phone: 800-555-1212
Email/Web: www.puco.ohio.gov

Report Number: OH3202000129
Inspection Date: 04/03/2025
Start: 01:50 PM EDT End: 02:30 PM EDT
Inspection Level: II Certification Date:
HM Inspection Type: None

RIK TRANSPORTATION INC
8225 LECLAIRE AVE
BURBANK, IL 60459
dba: BRZ
USDOT#: 3119062
MC/Mxt:
State:
Phone#: 7083035150
Fax#:

Driver: Acosta, Jonathan
License#: A223420791781
State#: FL
Date of Birth#: 05/18/1979
CoDriver:
License#:
State#:
Date of Birth#:

Location: Vandalia OH
MilePost: 64
Highway: Interstate 75
County: Montgomery County
Shipper: WASHINGTON PENN
Bill of Lading: 731331
Origin: LIVONIA, MI, US
Destination: LAFAYETTE, GA, US
Cargo: General Freight

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	Mileage	CVSA #	CVSA Issued #	OOS Sticker
1	TT	MACK	2020	IL	P1151462	811	1M1AN4GY1LM017928	52,000				
2	ST	HYTR	2022	IL	454775Z	W99432	3H3V532K6NS602685	68,000				

VIOLATIONS ATTRIBUTABLE TO THE MOTOR CARRIER

No Violations Were Discovered.

Special Checks:

Other

NOTE TO DRIVER: Within 24 hour this report must be furnished to the motor carrier whose name appears at the top of this report. [49 CFR 396.9(d)(1)]

Signature Of Motor Carrier Official X: _____

Date: _____

Other Driver / Carrier Notifications

***** POSSIBLE CDL DISQUALIFICATION *****

If this roadside inspection identified an alleged violation of one or more of the below noted regulations, your CDL may be disqualified. If the PUCO finds you committed a violation of any of these regulations, the violation will be treated as a conviction for the purposes of federal and state law and notice of such conviction will be forwarded to the Ohio Bureau of Motor Vehicles (BMV). The BMV may disqualify you from operating a commercial motor vehicle for a minimum of 60 days. Any BMV sanction is in addition to sanctions imposed by the Public Utilities Commission of Ohio (PUCO).

177.804E, 177.804B1, 177.804B2, 177.804B3, 177.804C, 49012-5-07D, 383.23A2-LCDLN, 383.23A2-LCDL, 383.23A2, 383.23A2-DT, 383.23A3-H, 383.23A2-P, 383.23A2-S, 383.23A2-R, 383.23A2-T, 383.25A5I, 383.25A5II, 383.51A-LCDLRSWD, 383.51A, 383.51A-SIN, 383.51A-SOUT, 383.51(E)(2), 383.91A-LCDL, 383.91A, 383.93B1, 383.93B2, 383.93B3, 383.93B4, 383.93B5, 391.11A, 391.11B5-LNCDLNVE, 391.11B5-LNCDLNVL, 391.11B5, 391.11B5-DEN, 391.11B5-DNL, 391.15A-LNCDLNLRW, 391.15A, 391.15A-SIN, 391.15A-SOUT, 392.10A1-RRR, 392.10A1, 392.10A2-RRR, 392.10A2, 392.10A3-RRR, 392.10A3, 392.10A4-RRR, 392.10A4, 392.10A5-RRR, 392.10A5, 392.10A6-RRR, 392.10A6, 392.11-RRR, 392.11, 392.12-RRR, 392.12, 2-5-07D, 392.4A-DOSU, 392.4A, 392.4A-POS, 392.4A-UI, 392.5A1-I, 392.5A2-IP, 392.5A2-UI, 392.5C2-1005, 392.5C2, 392.80-TEXTING, 392.80A, 392.82DUMT, 392.82A1, 395.13D, 395.13D1-OOSO, 395.13D1-DDOOS, 395.13D2-OOSO, 396.9C2-OOSO, 396.9C2

Report Prepared By:
J Whorton

Radio #: Radio #:
3202 3202

Copied Received By:
JONATHAN ACOSTA

Page 1 of 1

X

X



3119062 OH OH3202000129

MOTOR CARRIER INFORMATION

RIKI TRANSPORTATION INC
8225 LECLAIRE AVE
BURBANK, IL, 60459
dba: BRZ
USDOT#: 3119062
MC/MX#:
State#:
Phone#: 7083035150
Fax#:

Driver: Acosta, Jonathan
License# A223420791781
State# FL
Date of Birth# 05/18/1979
CoDriver:
License#
State#
Date of Birth#

Location: Vandalia OH
MilePost: 64
Highway: Interstate 75
County: Montgomery County
Shipper: WASHINGTON PENN
Bill of Lading: 731331
Origin: LIVONIA, MI, US
Destination: LAFAYETTE, GA, US
Cargo: General Freight

STATE INFORMATION

State Fields: Driver Address Verified?: Y; Driver Address: 1311 BIARRITZ DR; Driver City: MIAMI BEACH; Driver State: FL; Driver Zip: 33141; For Hire Carrier?: Y;
Reason Code: USSP; ISS Score: 45; Photos Taken?: ; Video Taken?: ; # of Fatalities: ; # of Injuries: ; Crash Report #: ; Supplemental Report #: ; Orig Seal
Placed by (C/D/S/U): ; Co-Investigator #: ; # of Passengers (PVI): ; MABI Inspection Exp. Date:
Hazard State Fields: HM Safety Permit Verified?: ; HM Incid/Crash w/ Release?: ; Placards Displayed?: ; Placards Offered?: ; Loaded by Carrier?: ; Loaded
by Shipper?: ; Ship Docs Prep by Carrier?: ; Ship Doc Prep by Shipper?:
Hazard List A: ID # (A): ; Packing Group (A): ; Gross Weight (A): ; Unit of Measure (A): ; MAR POL (A): ; Linked to Violation (A):
Hazard List B: ID (B): ; Packing Group (B): ; Gross Weight (B): ; Unit of Measure (B): ; MAR POL (B): ; Linked to Violation (B):
Hazard List C: ID (C): ; Packing Group (C): ; Gross Weight (C): ; Unit of Measure (C): ; MAR POL (C): ; Linked to Violation (C):
Hazard List D: ID (D): ; Packing Group (D): ; Gross Weight (D): ; Unit of Measure (D): ; MAR POL (D): ; Linked to Violation (D):
Hazard List E: ID (E): ; Packing Group (E): ; Gross Weight (E): ; Unit of Measure (E): ; MAR POL (E): ; Linked to Violation (E):
Hazard List F: ID (F): ; Packing Group (F): ; Gross Weight (F): ; Unit of Measure (F): ; MAR POL (F): ; Linked to Violation (F):

Report Prepared By:
J Whorton

Badge #: Radio #:
3202 3202

Copy Received By:
JONATHAN ACOSTA

