



NEW MEXICO DEPARTMENT OF PUBLIC SAFETY

COMMERCIAL VEHICLE ENFORCEMENT

P.O. BOX 1628
SANTA FE, NM 87504-1628Phone: (505) 827-9277
Fax: (505) 827-9279

cveinspection.certi@state.nm.us

DRIVER / VEHICLE EXAMINATION REPORT

INSPECTION NUMBER

NM8096P3AN02

Inspection Date

4/28/2025

Time Zone

MT

Time Started

5:30 PM

Time Ended

6:00 PM

Inspection Level

Level 2: Walk-Around Inspection

Location Description GALLUP PORT OF ENTRY		Highway 140	Milepost 12	County MCKINLEY
USDOT Number 02828543	MC Number	State Number		Facility Type F
Carrier Name ZIGI FREIGHT INC		Carrier Phone (630) 485-7370		Interstate Commerce? ☒ Yes ☐ No
Carrier Address 6850 W 63RD STREET		Carrier City CHICAGO		State IL
Shipper TOLLESON MIXING CENTER		Cargo Beverages - 01		Zip Code 60638
Origin City TOLLESON		Bill of Lading 21724933645		International Load? ☐ Yes ☐ No
Origin State AZ		Destination City RAPID CITY		Dest State SD
Cargo Seal Removed Yes	Cargo Seal Replaced Yes	Inspection Location Latitude 35.487051		Inspection Location Longitude -108.90248
☐ Border Enforcement Grant Funded ☐ ☐ ☐				

Special Checks

- | | | | |
|---|--|--|--------------------------------------|
| ☐ Alcohol/Controlled Substance Check | ☐ Traffic Enforcement | ☐ Size and Weight Enforcement | ☐ Drug Arrest |
| ☐ Conducted by Local Jurisdiction | ☐ Post Crash Inspection | ☐ E-Screening | ☐ Re-inspect |
| ☐ Drug Interdiction Search | ☐ PASA Conducted Inspection | ☐ PBST Inspection | |

Driver Status DRIVER	Last Name NINO HERRERA	First Name WILSON	Middle Name	DOB 12/15/1972	License Number N247382420000	State FL
VEHICLE INFORMATION						
Unit Type TT	Year 2023	Make FRHT	State IL	License # P1151456	Equipment ID unit 761	Unit VIN 3AKJHHR0PSUA1585
GYWR		CVSA #	Status	CVSA issued #	OOS Str #	
52 350						
Cargo Seal Removed ID		Cargo Seal Replaced ID				
2		ST 2026 GDA IL 631876T unit p5260125 1GR1P0627TJ806091 68,000				
Cargo Seal Removed ID		Cargo Seal Replaced ID				
0135562		NMSP0006911				
HAZARDOUS MATERIAL INFORMATION						
HM Unit	HazMat Inspection Type	Cargo Tank Type	HM Code	Reportable Quantity	Placards Required	HM Waste
VIOLATION INFORMATION						
Violation 1	Violation Unit	Violation Code	Violation Section	Violation Date	OOS	OOS Verified
Post Crash		Citation Type	Citation Num			
Violation Description						

No Violations Reported

*****NOTICE*****

If this box is checked, a separate traffic citation was issued to the violator. Please refer to the issued traffic citation for additional information. This is in addition to any action required by this report.

NOTICE TO CARRIER: PLEASE SIGN THE CERTIFICATION BELOW AND RETURN THIS REPORT TO NEW MEXICO STATE POLICE, COMMERCIAL VEHICLE ENFORCEMENT WITHIN FIFTEEN (15) DAYS. IF NO VIOLATIONS ARE NOTED ON THIS REPORT, DO NOT RETURN THE REPORT TO NMSP/CVE. PLEASE RETAIN IT FOR YOUR FILES.

The undersigned certifies that all violations noted on this report have been corrected and action has been taken to assure compliance with NMSA 1978 65-3-1 through 65-3-13, and the New Mexico Carrier Safety Regulations.

New Mexico Department Of Public Safety
Commercial Vehicle Enforcement
P.O. Box 1628
Santa Fe, NM 87504-1628
Fax: (505) 827-9279

Report Prepared By		I certify that the out of service violations listed in the "Violation Information" section have been satisfactorily repaired as of the date indicated. Failure to return this report with the required certification can result in penalties up to \$1,000.00 per day for each day the violation continues, up to a total of \$10,000.
TI L. THOLUND	308096	
Driver X	WILSON Nino 	Carrier X
		