

Tri State Truck Center, LLC

411 Hartford Turnpike Shrewsbury, MA 01545

Phone: (800) 395-8494: Parts - 1; Service - 2; Sales - 3; Leasing - 4

Fax: (508) 363-2641



ShrewsburyService@AdvantageTruckNE.com Eight Convenient Locations or Online at AdvantageTruckNE.com

MA: Raynham, Shrewsbury & Westfield NH: Lancaster, Lebanon, Manchester & Seabrook VT: Westminster

BILL TO ZIGI FREIGHT INC DBA Royal3 (RZZM8) - 50737 6850 W 63rd Street BEDFORD PARK IL 60638 P: (630) 566-0552 DELIVER TO ZIGI FREIGHT INC DBA Royal3 (RZZM8) - 50737 6850 W 63rd Street BEDFORD PARK IL 60638 P: (630) 566-0552

SERVICE ORDER: R101094702

PINNACLE: RZMM8

DA	ATE ARRIVED	DATE INVOICE	SALES TYPE	ADVISO		TERMS	CUSTOMER R	EFERENCE
9/2025	9:31:54AM		SPIN	GPETR	ROS	PINNACLE		
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	ENGINE HOURS	IN SERVICE	Component Serial #	ODOMETER
2022	FREIGHTLINER	PT 126 SLP	3AKJHHFG9NSNM4001	736	12,441			48000
			Sol	d Operations				
)B #	1 74	UNIT TOWED II	N - INSPECT ALL RE	CMOVED				
OMPL	AINT	UNIT TOWED IN - I	NSPECT ALL REMOVED	**				
AUSE		Unit Towed In For Re						
ORRE		Performed Post Tow I	-					
QTY	ITEM		DESCRIPTION				UNIT PRICE	EXTD PF
1	1641		[SUBLET]				810.00	810













Sold Operations (Cont.) **JOB #2 02** EXPRESS ASSESSMENT COMPLAINT EXPRESS ASSESSMENT ** CEL ACTIVE / CATALYST TANK REAGENT QUALITY - SPN(3364) - FMI(10) CAUSE Failed DEF Quality Sensor CORRECTION Unit Has Active Codes For Def Quality Sensor And Scr Derate Codes. Troubleshoot Code 4277 For Loss Of Communication With The Def Quality Sensor. Check Def Tank. About 1/2 Full. No Contamination Found. Def Quality Is At 32%. Perform Fault Code Verification And Code Is Still Active. No Ecm Calibration Updates For This Code Available. Def Quality Sensor Has Failed. Def Tank Header Will Need To Be Replaced And Fault Code Verifications Performed. Codes Will Then Need To Be Cleared And Unit Road Tested To Verify No Issues. Add To Estimate. Removed Step And Side Fairing. Removed Bumper And Drained Coolant. Disconnected Electric, Def And Coolant From Header. Removed Brace And Pulled Tank Out. Removed Top Cap And Removed Header. Installed New Header With New O-Ring And The Cap. Put Tank Back In. Hooked Up All Connections And Installed Brace. Installed Fairings And Step. Filled With Coolant And Installed Bumper. Steam Cleaned And Road Tested. No Codes Returned. Op Complete. Coverage: Customer Pay QTY ITEM DESCRIPTION UNIT PRICE EXTD PRICE LABOR 02 200.00 DIAGNOSTIC LABOR 100 EXPRESS REPAIR 1.012.50 1 101D/04-27530-000 O RING-UREA TANK, HEADER 22.16 22.16 101D/04-31353-005 HEADER-SSI,CONC,SAE FLG,CMNS 795.59 795.59 1 101D/OWI 23519396 9.25 9.25 1 POWERCOOL ELC 50/5 Subtotals: Prepay: 0.00 Parts: \$827.00 Labor: \$1,212.50 Misc: \$0.00 Sublet: \$0.00 \$2,039.50 JOB #3 71 **QUALITY CHECK QUALITY CHECK **** COMPLAINT CAUSE CORRECTION QC PASS / LABOR APPROVED MILEAGE: 480009 ITEM DESCRIPTION UNIT PRICE EXTD PRICE QTY LABOR 71 0.00 QUALITY CHECK \$0.00 Subtotals: Prepay: 0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 **Sold Operations Subtotals** Prepay: 0.00 Parts: \$827.00 Labor: \$1,212.50 Misc: \$0.00 Sublet: \$810.00 \$2,849.50













Page 2 of 3

FREIGHTLIN

AUTHORIZED BY

PRINTED NAME





DATE



62861 Collections Center Drive Chicago, IL 60693

ESTIMATED



NOT AN INVOICE



Please Remit Payment to: Pinnacle Fleet Solutions



Page 3 of 3





BILLED

\$1,212.50

\$3,004.25

PARTS		\$827.00
MISC		\$0.00
SUBLET		\$810.00
PREPAY		0.00
SUBTOTAL		\$2,849.50
SHOP SUPPLI	ES	\$97.00
MISC SUPPLIE	ES	\$0.00
TAX		\$57.75

LABOR

FINAL TOTAL

ESTIMATES VALID FOR 30 DAYS FROM DATE OF DOCUMENT. DISCLAIMER OF WARRANTIES: TRI STATE TRUCK CENTER, INC. MAKES NO ASSUMPTION OF WARRANTY FOR ANY PARTS, LABOR OR PREVIOUS REPAIRS PERFORMED AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON OR PERSONS TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THIS SALE. ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE MADE SOLELY BY THE MANUFACTURER. THE CUSTOMER AND/OR AGENT FOR THE CUSTOMER ACKNOWLEDGES RECEIPT OF ITEMS AND/OR SERVICES AND AGREES TO FINANCIAL RESPONSIBILITY FOR PAYMENT OF THIS INVOICE.