

PEACH STATE

TRUCK CENTERS

A subsidiary of Peach State Truck Centers
5884 Frontage Rd
FOREST PARK, GA 30297
P: (404) 366-8044

SERVICE ORDER: RA109022495

Key Tag Number: 6201

BILL TO
ROYAL 3 INC - 54223
6850 W 63RD ST
CHICAGO IL 60638
P: (414) 909-1836
ESTERASLISANDRO81@GMAIL.COM

DELIVER TO
ROYAL 3 INC - 54223
6850 W 63RD ST
CHICAGO IL 60638
P: (630) 485-7370
MAINTENANCE@ROYAL3INC.COM

ESTIMATE:16509475

DATE CREATE	DATE INVOICE	SALES TYPE	ADVISOR	TERMS	CUSTOMER PURCHASE ORDER		
11/1/2024		SR	ANGELA M F	CENPOS			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	IN SERVICE	Component Serial #	ODOMETER
2022	FTL	PT126SLP	3AKJHHFG0NSNM4002	737	5/6/2022	80387498	369277

Sold Operations

JOB #1 EA2-027 TRANSMISSION-AUTO DIAGNOSIS

COMPLAINT TRANSMISSION-AUTO DIAGNOSIS - TRANSMISSION-AUTO DIAGNOSIS ** UNIT GRINDING IN GEAR CAN NOT GO FORWARD OR REVERSE

CAUSE

CORRECTION 987 TOWED TRUCK IN SHOP, HOOKED UP COMPUTER AND STARTED CASE WITH EATON, WILL FOLLOW UP MONDAY, STARTED CASE WITH EATON ECT 4811358, HAVE ACTIVE RAIL C, REMOVED TRANS, MTM, TOOK PICS OF CAP SCREWS AND O-RINGS, REINSTALLED MTM, TRANS, DRIVE LINE, CALIBRATED MTM, ROAD TESTED AND PARKED

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	VMRS33	027-000-000		
1	COMP	CONN FEE		
1	ETN K 4637	MTM O-RING REPAIR CUSTOMER KIT		
	LABOR EA2	TRANSMISSION-AUTO DIAGNOSIS		

JOB #2 Recall Recall

COMPLAINT PERFORM RECALL ** FL958 A - BRAKE MODULATOR VALVES - PERFORM RECALL ** FL958 A - BRAKE MODULATOR VALVES

CAUSE

CORRECTION CK FOR RECALL STICKER IN DOOR JAM AND FOUND NONE, CK PART NUMBER ON MODULATOR VALVES AND THEY WERE BAD, REPLACED BOTH FRONT MODULATOR VALVES AND INSTALLED RECALL STICKER IN DOOR JAM

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	25-FL958-000	KIT,FL958,ANODIZED SMV		
	LABOR Recall	PERFORM RECALL ** FL958 A - BRAKE MODULATOR		

JOB #3 Recall Recall

COMPLAINT PERFORM RECALL ** SF685 A - COMMON TELEMATICS PLATFORM CUMMINS ENGINE - PERFORM RECALL ** SF685 A - COMMON TELEMATICS PLATFORM CUMMINS ENGINE

CAUSE

CORRECTION CK FOR RECALL STICKER AND FOUND NONE, REMOVED DASH PANELS, INSTALLED NEW CTP, INITIALIZED AND CK FOR ACTIVATION OK, SCREEN SHOT AND PUT WITH RO, INSTALLED RECALL STICKER IN DOOR JAM

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	25-SF685-000	KIT - SF685 CAMPAIGN		
	LABOR Recall	PERFORM RECALL ** SF685 A - COMMON TELEMATIC		

Sold Operations (Cont.)

JOB #4 024-002-000 Driveline Install (removed for towing)

COMPLAINT Driveline Install (removed for towing) -
CAUSE
CORRECTION 987 INSTALLED DRIVE LINE LEFT OUT BY TOW CO

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
	LABOR 024-002-000-DLI	Driveline Install (removed for towing)		

JOB #5 GEN General Diagnostic

COMPLAINT BRAKE LIGHT STUCK ON -
CAUSE
CORRECTION TEST DROVE AND FOUND CRUISE CONTROL WAS INOP, CK AND FOUND BRAKE LIGHTS ON ALL THE TIME, CK IMPUTES TO SSAM AND THEY ARE BEING COMMANDED WITH OUT PEDAL BEING DEPRESSED, REMOVED SWITCH AND MADE SURE NO AIR WAS ON SWITCH AND HAD NONE, OHMED WIRING TO SSAM AND HAD PROPER RESISTANCE, CONNECTED TEST SWITCH AND IT WORKS PROPERLY, REMOVED OLD SWITCH AND INSERT SPIN INSIDE MANIFOLD, REMOVED ALL AIR LINES AND DASH PANELS. R/R NEW PASS THRU MANIFOLD WITH NEW BRAKE LIGHT PRESSURE SWITCH, CK FOR LEAKS AND HAD NONE, TEST DROVE AND CRUISE CONTROL WORKS PROEPRLY NOW, CK LIGHTS AND THEY WORK PROPERLY ALSO

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	12-26964-002	PASSTHRU-SWITCH MANIFOLD, AIR		
1	12-27919-000	SWITCH-PRESSURE,NO 3.5 PSI		
	LABOR GEN	BRAKE LIGHT STUCK ON		

Sold Operations Totals Prepay: \$0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00 **\$0.00**

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY,DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

	ESTIMATED	BILLED
LABOR		\$0.00
PARTS		\$0.00
MISC		\$0.00
SUBLET		\$0.00
Prepay		\$0.00
SUBTOTAL		\$0.00
SHOP SUPPLIES		\$0.00
MISC SUPPLIES		\$0.00
TAX		\$0.00
TOTAL		\$0.00

X
SIGNATURE OF PERSON RESPONSIBLE OR AGENT FOR PERSON RESPONSIBLE FOR PAYMENT.

Please Remit Payment to:
6535 Crescent Dr
Norcross, GA 30071