

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

65650863

738

DATE

02/01/24

MOTOR CARRIER OPERATOR

INSPECTOR'S NAME (PRINT OR TYPE)

Zigi Freight Inc dba Royal 3 Inc

Jugoslav Kovalevic

ADDRESS

6850 W. 63rd St.

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☐ YES

CITY, STATE, ZIP CODE

Chicago, IL 60638

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

3AKJHHFG2NSNA4003

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS☐ (OTHER)

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System				b. Front End Structure				13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose								14. MOTORCOACH SEATS
✓			e. Brake Tubing								Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device								15. REAR IMPACT GUARD
			g. Tractor Protection Valve	✓			7. STEERING MECHANISM				In place, securely attached, proper size, proper placement (see 393.86).
			h. Air Compressor	✓			a. Steering Wheel Free Play	✓			16. OTHER
			i. Electric Brakes	✓			b. Steering Column				List any other condition(s) which may prevent safe operation of this vehicle.
			j. Hydraulic Brakes	✓			c. Front Axle Beam/All Other Steering Components				
			k. Vacuum Systems	✓			d. Steering Gear Box				
			l. Antilock Brake System	✓			e. Pitman Arm				
			m. Automatic Brake Adjusters	✓			f. Power Steering				
			2. COUPLING DEVICES	✓			g. Ball and Socket Joints				
			a. Fifth Wheels	✓			h. Tie Rods and Drag Links				
			b. Pintle Hooks	✓			i. Nuts				
			c. Drawbar/Towbar Eye	✓			j. Steering System				
			d. Drawbar/Towbar Tongue	✓			8. SUSPENSION				
			e. Safety Devices	✓			a. Axle Positioning Parts				
			f. Saddle-Mounts	✓			b. Spring Assembly				
			3. EXHAUST SYSTEM	✓			c. Torque, Radius or Tracking Components				
			a. No leaks forward of/ directly below the driver/sleeper compartment.	✓			9. FRAME				
			b. Bus: No leaking/ discharging in violation of standard.	✓			a. Frame Members				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			b. Tire and Wheel Clearance				
			4. FUEL SYSTEM	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
			a. No visible leak.	✓			10. TIRES				
			b. Fuel Tank Filler Cap	✓			a. Steer-Axle Tires				
			c. Fuel tank securely attached.	✓			b. All Other Tires				
			5. LIGHTING DEVICES	✓			c. Speed-Restricted Tires				
			All required lights/reflectors operable.	✓			11. WHEELS AND RIMS				
				✓			a. Lock or Side Ring				
				✓			b. Wheels and Rims				
				✓			c. Fasteners				
				✓			d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ X NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.