

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
62251381	739
DATE 03/08/2023	

MOTOR CARRIER OPERATOR ZIGI FREIGHT INC DBA ROYALZ INC	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOUACEVIC
ADDRESS 6850 W 63RD ST	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE CHICAGO IL 60638	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 3AKJHHFG4NSNM4004
VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
☒			a. Service Brakes
☒			b. Parking Brake System
☒			c. Brake Drums or Rotors
☒			d. Brake Hose
☒			e. Brake Tubing
☒			f. Low Pressure Warning Device
☒			g. Tractor Protection Valve
☒			h. Air Compressor
☒			i. Electric Brakes
☒			j. Hydraulic Brakes
☒			k. Vacuum Systems
☒			l. Antilock Brake System
☒			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
☒			a. Fifth Wheels
☒			b. Pintle Hooks
☒			c. Drawbar/Towbar Eye
☒			d. Drawbar/Towbar Tongue
☒			e. Safety Devices
☒			f. Saddle-Mounts
3. EXHAUST SYSTEM			
☒			a. No leaks forward of/ directly below the driver/ sleeper compartment.
☒			b. Bus: No leaking/ discharging in violation of standard.
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
4. FUEL SYSTEM			
☒			a. No visible leak.
☒			b. Fuel Tank Filler Cap
☒			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
☒			All required lights/reflectors operable.
6. SAFE LOADING			
☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
☒			b. Front End Structure
☒			c. Intermodal Container Securement Devices
7. STEERING MECHANISM			
☒			a. Steering Wheel Free Play
☒			b. Steering Column
☒			c. Front Axle Beam/All Other Steering Components
☒			d. Steering Gear Box
☒			e. Pitman Arm
☒			f. Power Steering
☒			g. Ball and Socket Joints
☒			h. Tie Rods and Drag Links
☒			i. Nuts
☒			j. Steering System
8. SUSPENSION			
☒			a. Axle Positioning Parts
☒			b. Spring Assembly
☒			c. Torque, Radius or Tracking Components
9. FRAME			
☒			a. Frame Members
☒			b. Tire and Wheel Clearance
☒			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
☒			a. Steer-Axle Tires
☒			b. All Other Tires
☒			c. Speed-Restricted Tires
11. WHEELS AND RIMS			
☒			a. Lock or Side Ring
☒			b. Wheels and Rims
☒			c. Fasteners
☒			d. Welds
12. WINDSHIELD GLAZING			
☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
13. WINDSHIELD WIPERS			
☒			No missing, damaged, or inoperable wipers.
14. MOTORCOACH SEATS			
☒			Seats securely fastened to the vehicle structure.
15. REAR IMPACT GUARD			
☒			In place, securely attached, proper size, proper placement (see 393.86).
16. OTHER			
List any other condition(s) which may prevent safe operation of this vehicle.			
PASS			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.