ANNUAL VEHICLE INSPECTION REPORT

| VEHICLE HIS | STORY RECORD | | |
|------------------|-------------------|--|--|
| REPORT NUMBER | FLEET UNIT NUMBER | | |
| 62784566 | 741 | | |
| DATE 02/17/2 | 2023 | | |

| The state of the s | | | |
|--|--|--|--|
| ZIGN FREIGHT INC DBA ROYALS INC | INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOUKCEUIC | | |
| 6850 W 63RD ST | THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. | | |
| CHICHGO 12 60638 | SAKJHHDRXPSWM3947 | | |
| VEHICLE TYPE TRACTOR TRAILER TRUCK BUS (OTHER) | INSPECTION AGENCY/LOCATION (OPTIONAL) | | |

| VEHICLE COMPONENTS INSPECTED | | | | | | |
|------------------------------|---|------------------------|---|--|--|--|
| OK NEEDS REPAIRED DATE | ITEM | OK NEEDS REPAIRED DATE | ITEM | OK NEEDS PEPA | TEM ITEM | |
| | 1. BRAKE SYSTEM | | 6. SAFE LOADING | Company of the | 12. WINDSHIELD GLAZING | |
| V | a. Service Brakes | | a. Vehicle parts, load, | | No cracks, discoloration, | |
| V | b. Parking Brake System | V | dunnage, spare tire, etc., | | obstacles, etc. (see 393.60 for | |
| | c. Brake Drums or Rotors | | secured. | | exceptions). | |
| V | d. Brake Hose | | b. Front End Structure | | 13. WINDSHIELD WIPERS | |
| V | e. Brake Tubing | WA | c. Intermodal Container | V | No missing, damaged, or | |
| V | f. Low Pressure Warning | / / / | Securement Devices | The second secon | inoperable wipers. | |
| | Device | | 7. STEERING MECHANISM | | 14. MOTORCOACH SEATS | |
| | g. Tractor Protection Valve | y | a. Steering Wheel Free Play | V | Seats securely fastened to the | |
| | h. Air Compressor | V | b. Steering Column | | vehicle structure. | |
| 1/1/ | i. Electric Brakes | V | c. Front Axle Beam/All | En al Alexandra | 15. REAR IMPACT GUARD | |
| MIN | j. Hydraulic Brakes | | Other Steering Components | 1//1 | In place, securely attached, | |
| | k. Vacuum Systems | 0 | d. Steering Gear Box | 1/14 | proper size, proper placement (see 393.86). | |
| 4 | Antilock Brake System | U | e. Pitman Arm | A | 16. OTHER | |
| V | m. Automatic Brake Adjusters | V | f. Power Steering | 1000 | List any other condition(s) | |
| 1 | 2. COUPLING DEVICES | V. | g. Ball and Socket Joints | | which may prevent safe | |
| 0 | a. Fifth Wheels | V | h. Tie Rods and Drag Links | | operation of this vehicle. | |
| | b. Pintle Hooks | V | i. Nuts | | | |
| 1)/4 | c. Drawbar/Towbar Eye | 1/ | j. Steering System | | | |
| 7 / 1 | d. Drawbar/Towbar Tongue | | 8. SUSPENSION | | | |
| V, | e. Safety Devices | V | a. Axle Positioning Parts | | | |
| V | f. Saddle-Mounts | | b. Spring Assembly | | | |
| | 3. EXHAUST SYSTEM | | | | | |
| | a. No leaks forward of/ | | c. Torque, Radius or Tracking | | | |
| V | directly below the driver/ | | Components 9. FRAME | | 169 | |
| | sleeper compartment. | V | | | 140 | |
| 11/1 | b. Bus: No leaking/ | | a. Frame Members | | 1/00 | |
| MA | discharging in violation of standard. | | b. Tire and Wheel Clearance | | | |
| | c. Unlikely to burn, char, | 11/1 | c. Adjustable Axle | | | |
| / | or damage the electrical | NA | Assemblies (Sliding | | | |
| V | wiring, fuel supply, or any | | Subframes) 10. TIRES | | | |
| (2) (2) | combustible part of vehicle. | | | | | |
| 1 | 4. FUEL SYSTEM | 1 | a. Steer-Axle Tires | | | |
| | a. No visible leak. | | b. All Other Tires | | | |
| | b. Fuel Tank Filler Cap | MA | c. Speed-Restricted Tires | | | |
| V | c. Fuel tank securely | | 11. WHEELS AND RIMS | | | |
| | attached. | V/ | a. Lock or Side Ring | | | |
| | 5. LIGHTING DEVICES | V | b. Wheels and Rims | | | |
| U | All required lights/reflectors | V | c. Fasteners | - Ph | | |
| | operable. | V | d. Welds | | | |
| INSTRUCTION | IS: MARK COLUMN ENTRIES TO VERIFY | INSPECTION: | OK, X NEEDS REPAIR, NA | IF ITEMS D | O NOT APPLY, REPAIRED DATE | |

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc. Neenah, Wi • JJKeller.com • (800) 327-6868 Printed in the USA