

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

68304434

751

DATE

1-13-2025

MOTOR CARRIER OPERATOR

ZIGI FREIGHT INC DBA ROYAL 3 INC

ADDRESS

6850 W 63RD ST

CITY, STATE, ZIP CODE

CHICAGO, IL 60638

VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

JUGOSLAV KOURCENIC

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER

3AKJH4DR6PSM 3962

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒	☐		1. BRAKE SYSTEM	☒	☐		6. SAFE LOADING	☒	☐		12. WINDSHIELD GLAZING
☒	☐		a. Service Brakes	☒	☐		a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒	☐		No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒	☐		b. Parking Brake System	☒	☐		b. Front End Structure	☒	☐		13. WINDSHIELD WIPERS
☒	☐		c. Brake Drums or Rotors	☒	☐		c. Intermodal Container Securement Devices	☒	☐		No missing, damaged, or inoperable wipers.
☒	☐		d. Brake Hose	☒	☐		7. STEERING MECHANISM	☒	☐		14. MOTORCOACH SEATS
☒	☐		e. Brake Tubing	☒	☐		a. Steering Wheel Free Play	☒	☐		Seats securely fastened to the vehicle structure.
☒	☐		f. Low Pressure Warning Device	☒	☐		b. Steering Column	☒	☐		15. REAR IMPACT GUARD
☒	☐		g. Tractor Protection Valve	☒	☐		c. Front Axle Beam/All Other Steering Components	☒	☐		In place, securely attached, proper size, proper placement (see 393.86).
☒	☐		h. Air Compressor	☒	☐		d. Steering Gear Box	☒	☐		16. OTHER
☒	☐		i. Electric Brakes	☒	☐		e. Pitman Arm	☒	☐		List any other condition(s) which may prevent safe operation of this vehicle.
☒	☐		j. Hydraulic Brakes	☒	☐		f. Power Steering	☒	☐		PASS
☒	☐		k. Vacuum Systems	☒	☐		g. Ball and Socket Joints	☒	☐		
☒	☐		l. Antilock Brake System	☒	☐		h. Tie Rods and Drag Links	☒	☐		
☒	☐		m. Automatic Brake Adjusters	☒	☐		i. Nuts	☒	☐		
☒	☐		2. COUPLING DEVICES	☒	☐		j. Steering System	☒	☐		
☒	☐		a. Fifth Wheels	☒	☐		8. SUSPENSION	☒	☐		
☒	☐		b. Pintle Hooks	☒	☐		a. Axle Positioning Parts	☒	☐		
☒	☐		c. Drawbar/Towbar Eye	☒	☐		b. Spring Assembly	☒	☐		
☒	☐		d. Drawbar/Towbar Tongue	☒	☐		c. Torque, Radius or Tracking Components	☒	☐		
☒	☐		e. Safety Devices	☒	☐		9. FRAME	☒	☐		
☒	☐		f. Saddle-Mounts	☒	☐		a. Frame Members	☒	☐		
☒	☐		3. EXHAUST SYSTEM	☒	☐		b. Tire and Wheel Clearance	☒	☐		
☒	☐		a. No leaks forward of/ directly below the driver/sleeper compartment.	☒	☐		c. Adjustable Axle Assemblies (Sliding Subframes)	☒	☐		
☒	☐		b. Bus: No leaking/ discharging in violation of standard.	☒	☐		10. TIRES	☒	☐		
☒	☐		c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒	☐		a. Steer-Axle Tires	☒	☐		
☒	☐		4. FUEL SYSTEM	☒	☐		b. All Other Tires	☒	☐		
☒	☐		a. No visible leak.	☒	☐		c. Speed-Restricted Tires	☒	☐		
☒	☐		b. Fuel Tank Filler Cap	☒	☐		11. WHEELS AND RIMS	☒	☐		
☒	☐		c. Fuel tank securely attached.	☒	☐		a. Lock or Side Ring	☒	☐		
☒	☐		5. LIGHTING DEVICES	☒	☐		b. Wheels and Rims	☒	☐		
☒	☐		All required lights/reflectors operable.	☒	☐		c. Fasteners	☒	☐		
☒	☐			☒	☐		d. Welds	☒	☐		

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, ☐ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.