

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
66550447	756
DATE 02/06/27	

MOTOR CARRIER OPERATOR Zig Fajal inc DBA Royal 3 inc	INSPECTOR'S NAME (PRINT OR TYPE) Jugoslav Kovacevic
ADDRESS 6850 W. 63RD ST	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE CHICAGO, IL 60638	VEHICLE IDENTIFICATION (IF AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER 3AK3HHDR05NM 756
VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒			1. BRAKE SYSTEM	☒			6. SAFE LOADING	☒			12. WINDSHIELD GLAZING
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			b. Parking Brake System				b. Front End Structure	☒			13. WINDSHIELD WIPERS
☒			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	☒			No missing, damaged, or inoperable wipers.
☒			d. Brake Hose				7. STEERING MECHANISM	☒			14. MOTORCOACH SEATS
☒			e. Brake Tubing				a. Steering Wheel Free Play	☒			Seats securely fastened to the vehicle structure.
☒			f. Low Pressure Warning Device				b. Steering Column				15. REAR IMPACT GUARD
☒			g. Tractor Protection Valve				c. Front Axle Beam/All Other Steering Components				In place, securely attached, proper size, proper placement (see 393.86).
☒			h. Air Compressor				d. Steering Gear Box				16. OTHER
☒			i. Electric Brakes				e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
☒			j. Hydraulic Brakes				f. Power Steering				
☒			k. Vacuum Systems				g. Ball and Socket Joints				
☒			l. Antilock Brake System				h. Tie Rods and Drag Links				
☒			m. Automatic Brake Adjusters				i. Nuts				
☒			2. COUPLING DEVICES				j. Steering System				
☒			a. Fifth Wheels				8. SUSPENSION				
☒			b. Pintle Hooks				a. Axle Positioning Parts				
☒			c. Drawbar/Towbar Eye				b. Spring Assembly				
☒			d. Drawbar/Towbar Tongue				c. Torque, Radius or Tracking Components				
☒			e. Safety Devices				9. FRAME				
☒			f. Saddle-Mounts				a. Frame Members				
☒			3. EXHAUST SYSTEM				b. Tire and Wheel Clearance				
☒			a. No leaks forward of/ directly below the driver/ sleeper compartment.				c. Adjustable Axle Assemblies (Sliding Subframes)				
☒			b. Bus: No leaking/ discharging in violation of standard.				10. TIRES				
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				a. Steer-Axle Tires				
☒			4. FUEL SYSTEM				b. All Other Tires				
☒			a. No visible leak.				c. Speed-Restricted Tires				
☒			b. Fuel Tank Filler Cap				11. WHEELS AND RIMS				
☒			c. Fuel tank securely attached.				a. Lock or Side Ring				
☒			5. LIGHTING DEVICES				b. Wheels and Rims				
☒			All required lights/reflectors operable.				c. Fasteners				
☒							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ X NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

Copyright 2022 J. J. Keller & Associates, Inc.
Nienah, WI • JJKeller.com • (800) 327-6868
Printed in the USA

VEHICLE COPY

2241
(Rev. 1/22)