

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

67129258

915

DATE

08/15/24

MOTOR CARRIER OPERATOR

Zig. Freight Inc dba Royal 3m Jugoscrv Kovalevic

ADDRESS

6850 W. 63rd St.

CITY, STATE, ZIP CODE

Chicago, IL 60638

INSPECTOR'S NAME (PRINT OR TYPE)

Jugoscrv Kovalevic

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

4V4NC9EH4NN287289

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS☐ (OTHER)

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System				b. Front End Structure				13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose								14. MOTORCOACH SEATS
✓			e. Brake Tubing								Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device								15. REAR IMPACT GUARD
			g. Tractor Protection Valve								In place, securely attached, proper size, proper placement (see 393.86).
N/A			h. Air Compressor	✓			a. Steering Wheel Free Play	✓			16. OTHER
N/A			i. Electric Brakes	✓			b. Steering Column				List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes				c. Front Axle Beam/All Other Steering Components				
✓			k. Vacuum Systems	✓			d. Steering Gear Box				
✓			l. Antilock Brake System	✓			e. Pitman Arm				
✓			m. Automatic Brake Adjusters	✓			f. Power Steering				
			2. COUPLING DEVICES				7. STEERING MECHANISM				
✓			a. Fifth Wheels	✓			g. Ball and Socket Joints				
N/A			b. Pintle Hooks	✓			h. Tie Rods and Drag Links				
✓			c. Drawbar/Towbar Eye	✓			i. Nuts				
✓			d. Drawbar/Towbar Tongue	✓			j. Steering System				
✓			e. Safety Devices	✓							
✓			f. Saddle-Mounts	✓			8. SUSPENSION				
			3. EXHAUST SYSTEM				a. Axle Positioning Parts				
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.	✓			b. Spring Assembly				
N/A			b. Bus: No leaking/ discharging in violation of standard.	✓			c. Torque, Radius or Tracking Components				
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			9. FRAME				
			4. FUEL SYSTEM				a. Frame Members				
✓			a. No visible leak.	✓			b. Tire and Wheel Clearance				
✓			b. Fuel Tank Filler Cap	✓			c. Adjustable Axle Assemblies (Sliding Subframes)				
✓			c. Fuel tank securely attached.	✓			10. TIRES				
			5. LIGHTING DEVICES				a. Steer-Axle Tires				
✓			All required lights/reflectors operable.	✓			b. All Other Tires				
							c. Speed-Restricted Tires				
							11. WHEELS AND RIMS				
							a. Lock or Side Ring				
							b. Wheels and Rims				
							c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.