## **ANNUAL VEHICLE INSPECTION REPORT**

VEHICLE HISTORY RECORD									
REPORT NUMBER	FLEET UNIT NUMBER								
DATE									

MOTOR CARRIER OPERATOR  ZIGI FREIGHT INC dba ROYAL3 INC	INSPECTOR'S NAME (PRINT OR TYPE)  JUGOSLAV KOVACEVIC					
ADDRESS 6850 W. 63rd STREET	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.  ✓ YES					
CHICAGO, IL 60638	VEHICLE INDETIFICATION ( ✓ AND COMPLETE) ☐ LIC.PLATE NO. ☑ VIN ☐ OTHER					
VEHICLE TYPE ■ TRACTOR □ TRAILER □ TRUCK □ BUS □ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)					

☐ (OTHER)											
						VEHICLE	COMPONENTS INSPECTED				
ОК	NEEDS REPAIR	REPAIRED	ITEM	ОК	NEEDS REPAIR	REPAIRED	ITEM	ОК	NEEDS REPAIR	REPAIRED	ITEM
	REPAIR	DATE	1. BRAKE SYSTEM		REPAIR	DATE	6. SAFE LOADING		REPAIR	DATE	12. WINDSHEILD GLAZING
			a. Service Brakes				a. Vehicle parts, load,				No cracks, discoloration,
			b. Parking Brake System				dunnage, spare tire, etc., secured.				obstacles, etc. (see 393.60 for
			c. Brake Drums or Rotors				Scourcu.				exceptions).
			d. Brake Hose			N/A	b. Front End Structure				13. WINDSHEILD WIPERS
✓			e. Brake Tubbing		)	N/A	c. Intermodal Container				No missing, Damaged, or
			f. Low Pressure Warning			N/A	Securement Devices				inoperable wipers.
	נ		Device				7. STEERING MECHANISM				14. MOTORCOACH SEATS
			g. Tractor Protection Valve				a. Steering Wheel Free Play				Seats securely fastened to the vehicle
			h. Air Compressor				b. Steering Column	_			structure.
		N/A	i. Electric Brakes				C. Front Axle Beam/All				15. REAR IMPACT GUARD
		N/A	j. Hydraulic Brakes				Other Steering Components				In place convenients about preparation
		N/A	k. Vakum Systems				d. Steering Gear Box			N/A	In place, securely attached, proper size, proper placement (see 393.86).
			I. Antilock Brake System				e. Pitman Arm				
			m. Automatic Brake Adjusters				f. Power Steering				16. OTHER
			2. COUPLING DEVICES				g. Ball and Socket Joints				List any other condition(s) which may prevent safe
			a. Fifth Wheels				h. Tie Rods and Drag Links				operation of this vehicle.
		N/A	b. Pintle Hooks				i. Nuts				
		N/A	c. Drawbar/Towbar Eye				j. Streering System				
		N/A	d. Drawbar/Towbar Tongue				8. SUSPENSION				
			e. Safety Devices				a. Axle Positioning Parts				
✓			f. Saddle-Mounts				b. Spring Assembly				
			3. EXHAUST SYSTEM				c. Torque, Radius or Tracking Components				
			<ul> <li>a. No leaks forward of/ directly below the driver/</li> </ul>				Components				
			sleeper compartment.				9. FRAME				
							a. Frame Members				// Luggen/l
			<ul> <li>b. Bus: No leaking/</li> <li>discharging in violation of</li> </ul>				b. Tire and Wheel Clearance				
		N/A	standard.				c. Adjustable Axle Assemblies (Sliding Subframes)				
						N/A	Assemblies (Silding Subtrames)				
			<ul> <li>c. Unlikely to burn, char,</li> <li>or damage the electrical</li> </ul>								
✓			wiring, fuel supply, or any				10. TIRES				
			combustible part of vehicle.				a. Steer-Axle Tires				
			4. FUEL SYSTEM				b. All Other Tires				
			a. No visible Leak.			N/A	c. Speed-Restricted Tires				
			b. Fuel tank filler cap				11. WHEELS AND RIMS				
☑			c. Fuel tank securely attached.				a. Lock or Side Ring				
			5. LIGHTING DEVICES				b. Wheels and Rims				
			<ul> <li>a. All required light/reflectors operable.</li> </ul>				c. Fasteners				
	J		υμειανίε.				d. Welds				
INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: VOK, NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE											

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.