

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
65188829	821
DATE 4/15/2024	

MOTOR CARRIER OPERATOR Riki Transportation DBA BRZ	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOVACEVIC
ADDRESS 6850 W 63RD ST	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE CHICAGO, IL 60638	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☐ VIN ☐ OTHER 1M1AN4GJXLMO17944
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED							
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
☒			1. BRAKE SYSTEM	☒			6. SAFE LOADING
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
☒			b. Parking Brake System	☒			b. Front End Structure
☒			c. Brake Drums or Rotors	☒			c. Intermodal Container Securement Devices
☒			d. Brake Hose	☒			7. STEERING MECHANISM
☒			e. Brake Tubing	☒			a. Steering Wheel Free Play
☒			f. Low Pressure Warning Device	☒			b. Steering Column
☒			g. Tractor Protection Valve	☒			c. Front Axle Beam/All Other Steering Components
☒			h. Air Compressor	☒			d. Steering Gear Box
☒			i. Electric Brakes	☒			e. Pitman Arm
☒			j. Hydraulic Brakes	☒			f. Power Steering
☒			k. Vacuum Systems	☒			g. Ball and Socket Joints
☒			l. Antilock Brake System	☒			h. Tie Rods and Drag Links
☒			m. Automatic Brake Adjusters	☒			i. Nuts
☒			2. COUPLING DEVICES	☒			j. Steering System
☒			a. Fifth Wheels	☒			8. SUSPENSION
☒			b. Pintle Hooks	☒			a. Axle Positioning Parts
☒			c. Drawbar/Towbar Eye	☒			b. Spring Assembly
☒			d. Drawbar/Towbar Tongue	☒			c. Torque, Radius or Tracking Components
☒			e. Safety Devices	☒			9. FRAME
☒			f. Saddle-Mounts	☒			a. Frame Members
☒			3. EXHAUST SYSTEM	☒			b. Tire and Wheel Clearance
☒			a. No leaks forward of/ directly below the driver/ sleeper compartment.	☒			c. Adjustable Axle Assemblies (Sliding Subframes)
☒			b. Bus: No leaking/ discharging in violation of standard.	☒			10. TIRES
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒			a. Steer-Axle Tires
☒			4. FUEL SYSTEM	☒			b. All Other Tires
☒			a. No visible leak.	☒			c. Speed-Restricted Tires
☒			b. Fuel Tank Filler Cap	☒			11. WHEELS AND RIMS
☒			c. Fuel tank securely attached.	☒			a. Lock or Side Ring
☒			5. LIGHTING DEVICES	☒			b. Wheels and Rims
☒			All required lights/reflectors operable.	☒			c. Fasteners
				☒			d. Welds
							12. WINDSHIELD GLAZING
							No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
							13. WINDSHIELD WIPERS
							No missing, damaged, or inoperable wipers.
							14. MOTORCOACH SEATS
							Seats securely fastened to the vehicle structure.
							15. REAR IMPACT GUARD
							In place, securely attached, proper size, proper placement (see 393.86).
							16. OTHER
							List any other condition(s) which may prevent safe operation of this vehicle.
							PASS

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.