

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

67123256

703

DATE

08/13/24

MOTOR CARRIER OPERATOR

Zigi Freight Inc dba Royal 3 inc

ADDRESS

6850 W. 63rd St.

CITY, STATE, ZIP CODE

Chicago, IL 60638

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS
☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

Jugoslav Kovacevic

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

1MAN4GY5LM008195

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System				b. Front End Structure	✓			13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose				7. STEERING MECHANISM	✓			14. MOTORCOACH SEATS
✓			e. Brake Tubing				a. Steering Wheel Free Play	✓			Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device				b. Steering Column				15. REAR IMPACT GUARD
✓			g. Tractor Protection Valve				c. Front Axle Beam/All Other Steering Components				In place, securely attached, proper size, proper placement (see 393.86).
✓			h. Air Compressor				d. Steering Gear Box				16. OTHER
✓			i. Electric Brakes				e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes				f. Power Steering				
✓			k. Vacuum Systems				g. Ball and Socket Joints				
✓			l. Antilock Brake System				h. Tie Rods and Drag Links				
✓			m. Automatic Brake Adjusters				i. Nuts				
✓			2. COUPLING DEVICES				j. Steering System				
✓			a. Fifth Wheels				8. SUSPENSION				
✓			b. Pintle Hooks				a. Axle Positioning Parts				
✓			c. Drawbar/Towbar Eye				b. Spring Assembly				
✓			d. Drawbar/Towbar Tongue				c. Torque, Radius or Tracking Components				
✓			e. Safety Devices				9. FRAME				
✓			f. Saddle-Mounts				a. Frame Members				
✓			3. EXHAUST SYSTEM				b. Tire and Wheel Clearance				
✓			a. No leaks forward of/ directly below the driver/sleeper compartment.				c. Adjustable Axle Assemblies (Sliding Subframes)				
✓			b. Bus: No leaking/ discharging in violation of standard.				10. TIRES				
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				a. Steer-Axle Tires				
✓			4. FUEL SYSTEM				b. All Other Tires				
✓			a. No visible leak.				c. Speed-Restricted Tires				
✓			b. Fuel Tank Filler Cap				11. WHEELS AND RIMS				
✓			c. Fuel tank securely attached.				a. Lock or Side Ring				
✓			5. LIGHTING DEVICES				b. Wheels and Rims				
✓			All required lights/reflectors operable.				c. Fasteners				
✓							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.