

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER	DATE
66681529	824	5/20/2024

MOTOR CARRIER OPERATOR Riki Transportation INC DBA BRZ	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOVACEVIC
ADDRESS 8225 LECLAIRE AVE	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE BURBANK, CA 91502	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN 1M1AU46Y4LM017938
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			1. BRAKE SYSTEM	✓			e. Pitman Arm
✓			a. Service Brakes	✓			f. Power Steering
✓			b. Parking Brake System	✓			g. Ball and Socket Joints
✓			c. Brake Drums or Rotors	✓			h. Tie Rods and Drag Links
✓			d. Brake Hose	✓			i. Nuts
✓			e. Brake Tubing	✓			j. Steering System
✓			f. Low Pressure Warning Device	✓			8. SUSPENSION
N/A			g. Tractor Protection Valve	✓			a. Axle Positioning Parts
N/A			h. Air Compressor	✓			b. Spring Assembly
✓			i. Electric Brakes	N/A			c. Torque, Radius or Tracking Components
✓			j. Hydraulic Brakes	✓			9. FRAME
✓			k. Vacuum Systems	✓			a. Frame Members
✓			l. Antilock Brake System	✓			b. Tire and Wheel Clearance
✓			m. Automatic Brake Adjusters	✓			c. Adjustable Axle Assemblies (Sliding Subframes)
✓			2. COUPLING DEVICES	✓			10. TIRES
✓			a. Fifth Wheels	✓			a. Steer-Axle Tires
N/A			b. Pintle Hooks	✓			b. All Other Tires
✓			c. Drawbar/Towbar Eye	✓			c. Speed-Restricted Tires
✓			d. Drawbar/Towbar Tongue	✓			11. WHEELS AND RIMS
✓			e. Safety Devices	✓			a. Lock or Side Ring
✓			f. Saddle-Mounts	✓			b. Wheels and Rims
✓			3. EXHAUST SYSTEM	✓			c. Fasteners
✓			a. No leaks forward of/directly below the driver/sleeper compartment.	✓			d. Welds
N/A			b. Bus: No leaking/discharging in violation of standard.	✓			12. WINDSHIELD GLAZING
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			4. FUEL SYSTEM	✓			13. WINDSHIELD WIPERS
✓			a. No visible leak.	✓			Any power unit that has an inoperative wiper, or missing or damaged parts that render it ineffective.
✓			b. Fuel Tank Filler Cap	✓			14. MOTORCOACH SEATS
✓			c. Fuel tank securely attached.	✓			Any passenger seat that is not securely fastened to the vehicle structure.
✓			5. LIGHTING DEVICES	✓			15. REAR IMPACT GUARD
✓			All lighting devices and reflectors required by Section 393 shall be operable.	N/A			In place, securely attached, proper size, proper placement (see 393.86).
✓			6. SAFE LOADING	✓			16. OTHER
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			List any other condition(s) which may prevent safe operation of this vehicle.
✓			b. Front End Structure	✓			
✓			c. Intermodal Container Securement Devices	✓			
✓			7. STEERING MECHANISM	✓			
✓			a. Steering Wheel Free Play	✓			
✓			b. Steering Column	✓			
✓			c. Front Axle Beam/All Other Steering Components	✓			
✓			d. Steering Gear Box	✓			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.