

## ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
68304414	832
DATE 12/05/24	

MOTOR CARRIER OPERATOR <b>Piki TRANSPORTATION inc dba BRZ</b>	INSPECTOR'S NAME (PRINT OR TYPE) <b>Jugoslav Kovalevic</b>
ADDRESS <b>8225 CECLAIRE AVE.</b>	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. <input checked="" type="checkbox"/> YES
CITY, STATE, ZIP CODE <b>BURBANK, IL 60459</b>	VEHICLE IDENTIFICATION (✓ AND COMPLETE) <input type="checkbox"/> LIC. PLATE NO. <input checked="" type="checkbox"/> VIN <input type="checkbox"/> OTHER
VEHICLE TYPE <input type="checkbox"/> TRACTOR <input type="checkbox"/> TRAILER <input checked="" type="checkbox"/> TRUCK <input type="checkbox"/> BUS <input type="checkbox"/> (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL) <b>1M1AN9GYSNH023460</b>

VEHICLE COMPONENTS INSPECTED			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
<b>1. BRAKE SYSTEM</b>			
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
✓			f. Low Pressure Warning Device
✓			g. Tractor Protection Valve
✓			h. Air Compressor
✓			i. Electric Brakes
✓			j. Hydraulic Brakes
✓			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
<b>2. COUPLING DEVICES</b>			
✓			a. Fifth Wheels
✓			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
✓			d. Drawbar/Towbar Tongue
✓			e. Safety Devices
✓			f. Saddle-Mounts
<b>3. EXHAUST SYSTEM</b>			
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.
✓			b. Bus: No leaking/ discharging in violation of standard.
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
<b>4. FUEL SYSTEM</b>			
✓			a. No visible leak.
✓			b. Fuel Tank Filler Cap
✓			c. Fuel tank securely attached.
<b>5. LIGHTING DEVICES</b>			
✓			All required lights/reflectors operable.
<b>6. SAFE LOADING</b>			
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
✓			c. Intermodal Container Securement Devices
<b>7. STEERING MECHANISM</b>			
✓			a. Steering Wheel Free Play
✓			b. Steering Column
✓			c. Front Axle Beam/All Other Steering Components
✓			d. Steering Gear Box
✓			e. Pitman Arm
✓			f. Power Steering
✓			g. Ball and Socket Joints
✓			h. Tie Rods and Drag Links
✓			i. Nuts
✓			j. Steering System
<b>8. SUSPENSION</b>			
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
<b>9. FRAME</b>			
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
<b>10. TIRES</b>			
✓			a. Steer-Axle Tires
✓			b. All Other Tires
✓			c. Speed-Restricted Tires
<b>11. WHEELS AND RIMS</b>			
✓			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds
<b>12. WINDSHIELD GLAZING</b>			
✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
<b>13. WINDSHIELD WIPERS</b>			
✓			No missing, damaged, or inoperable wipers.
<b>14. MOTORCOACH SEATS</b>			
✓			Seats securely fastened to the vehicle structure.
<b>15. REAR IMPACT GUARD</b>			
✓			In place, securely attached, proper size, proper placement (see 393.86).
<b>16. OTHER</b>			
List any other condition(s) which may prevent safe operation of this vehicle.			
<p><b>P</b></p> <p><b>PASSED</b></p>			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☐ NEEDS REPAIR, ☐ NA IF ITEMS DO NOT APPLY, ☐ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.