ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
67129260	850
DATE	08/16/24

MOTOR CARRIER OPERATOR: RIKI TRANSPORTATION INC dba BRZ	INSPECTOR'S NAME (PRINT OR TYPE): JUGOSCAV KOVACEVIC
ADDRESS: 825 CECIRE AVE.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES
CITY, STATE, ZIP CODE: BURBANK, IL 60459	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER: 1M1AN4GYXPM031932
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☑ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
✓			f. Low Pressure Warning Device
N/A			g. Tractor Protection Valve
			h. Air Compressor
N/A			i. Electric Brakes
			j. Hydraulic Brakes
			k. Vacuum Systems
✓			l. Antilock Brake System
			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
✓			a. Fifth Wheels
			b. Pintle Hooks
N/A			c. Drawbar/Towbar Eye
			d. Drawbar/Towbar Tongue
✓			e. Safety Devices
			f. Saddle-Mounts
3. EXHAUST SYSTEM			
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.
N/A			b. Bus: No leaking/ discharging in violation of standard.
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
4. FUEL SYSTEM			
✓			a. No visible leak.
✓			b. Fuel Tank Filler Cap
✓			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
✓			All required lights/reflectors operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
6. SAFE LOADING			
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
			b. Front End Structure
N/A			c. Intermodal Container Securement Devices
7. STEERING MECHANISM			
✓			a. Steering Wheel Free Play
✓			b. Steering Column
✓			c. Front Axle Beam/All Other Steering Components
✓			d. Steering Gear Box
✓			e. Pitman Arm
✓			f. Power Steering
✓			g. Ball and Socket Joints
✓			h. Tie Rods and Drag Links
✓			i. Nuts
✓			j. Steering System
8. SUSPENSION			
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
9. FRAME			
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
N/A			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
✓			a. Steer-Axle Tires
✓			b. All Other Tires
N/A			c. Speed-Restricted Tires
11. WHEELS AND RIMS			
N/A			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
12. WINDSHIELD GLAZING			
✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
13. WINDSHIELD WIPERS			
✓			No missing, damaged, or inoperable wipers.
14. MOTORCOACH SEATS			
✓			Seats securely fastened to the vehicle structure.
15. REAR IMPACT GUARD			
N/A			In place, securely attached, proper size, proper placement (see 393.86).
16. OTHER			
			List any other condition(s) which may prevent safe operation of this vehicle.

PASSED

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.

ORIGINAL