

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
67086045	605
DATE 08/03/24	

MOTOR CARRIER OPERATOR Rick TRANSPORTATION in dba BRT	INSPECTOR'S NAME (PRINT OR TYPE) Jugoslav KOVALEVIC
ADDRESS 8225 LECIAIRE AVE.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE BURBANK, IL 60459	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. 3AKJH-DR-7PSUA-1597 ☒ OTHER
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED											
OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
			a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			b. Parking Brake System				b. Front End Structure				13. WINDSHIELD WIPERS
			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices				No missing, damaged, or inoperable wipers.
			d. Brake Hose								14. MOTORCOACH SEATS
			e. Brake Tubing								Seats securely fastened to the vehicle structure.
			f. Low Pressure Warning Device				7. STEERING MECHANISM				15. REAR IMPACT GUARD
			g. Tractor Protection Valve				a. Steering Wheel Free Play				In place, securely attached, proper size, proper placement (see 393.86).
			h. Air Compressor				b. Steering Column				16. OTHER
			i. Electric Brakes				c. Front Axle Beam/All Other Steering Components				List any other condition(s) which may prevent safe operation of this vehicle.
			j. Hydraulic Brakes				d. Steering Gear Box				
			k. Vacuum Systems				e. Pitman Arm				
			l. Antilock Brake System				f. Power Steering				
			m. Automatic Brake Adjusters				g. Ball and Socket Joints				
			2. COUPLING DEVICES				h. Tie Rods and Drag Links				
			a. Fifth Wheels				i. Nuts				
			b. Pintle Hooks				j. Steering System				
			c. Drawbar/Towbar Eye				8. SUSPENSION				
			d. Drawbar/Towbar Tongue				a. Axle Positioning Parts				
			e. Safety Devices				b. Spring Assembly				
			f. Saddle-Mounts				c. Torque, Radius or Tracking Components				
			3. EXHAUST SYSTEM				9. FRAME				
			a. No leaks forward of/ directly below the driver/ sleeper compartment.				a. Frame Members				
			b. Bus: No leaking/ discharging in violation of standard.				b. Tire and Wheel Clearance				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				c. Adjustable Axle Assemblies (Sliding Subframes)				
			4. FUEL SYSTEM				10. TIRES				
			a. No visible leak.				a. Steer-Axle Tires				
			b. Fuel Tank Filler Cap				b. All Other Tires				
			c. Fuel tank securely attached.				c. Speed-Restricted Tires				
			5. LIGHTING DEVICES				11. WHEELS AND RIMS				
			All required lights/reflectors operable.				a. Lock or Side Ring				
							b. Wheels and Rims				
							c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, ☐ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.