

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
68504415	555
DATE 12/06/24	

MOTOR CARRIER OPERATOR Big Freight Inc dba Royal 3 Inc	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOVACERIK
ADDRESS 6850 W. 63RD.	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE Chicago, IL 60638	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS ☐ (OTHER)	VEHICLE IDENTIFICATION (✓ AND COMPLETE) 4V4NC9GH66N416664 INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
✓			f. Low Pressure Warning Device
✓			g. Tractor Protection Valve
✓			h. Air Compressor
✓			i. Electric Brakes
✓			j. Hydraulic Brakes
✓			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
✓			a. Fifth Wheels
✓			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
✓			d. Drawbar/Towbar Tongue
✓			e. Safety Devices
✓			f. Saddle-Mounts
3. EXHAUST SYSTEM			
✓			a. No leaks forward of/ directly below the driver/ sleeper compartment.
✓			b. Bus: No leaking/ discharging in violation of standard.
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
4. FUEL SYSTEM			
✓			a. No visible leak.
✓			b. Fuel Tank Filler Cap
✓			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
✓			All required lights/reflectors operable.
6. SAFE LOADING			
✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
✓			c. Intermodal Container Securement Devices
7. STEERING MECHANISM			
✓			a. Steering Wheel Free Play
✓			b. Steering Column
✓			c. Front Axle Beam/All Other Steering Components
✓			d. Steering Gear Box
✓			e. Pitman Arm
✓			f. Power Steering
✓			g. Ball and Socket Joints
✓			h. Tie Rods and Drag Links
✓			i. Nuts
✓			j. Steering System
8. SUSPENSION			
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
9. FRAME			
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
✓			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
✓			a. Steer-Axle Tires
✓			b. All Other Tires
✓			c. Speed-Restricted Tires
11. WHEELS AND RIMS			
✓			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds
12. WINDSHIELD GLAZING			
✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
13. WINDSHIELD WIPERS			
✓			No missing, damaged, or inoperable wipers.
14. MOTORCOACH SEATS			
✓			Seats securely fastened to the vehicle structure.
15. REAR IMPACT GUARD			
✓			In place, securely attached, proper size, proper placement (see 393.86).
16. OTHER			
List any other condition(s) which may prevent safe operation of this vehicle.			
PASSED			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.