

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
68304412	607
DATE 11/25/24	

MOTOR CARRIER OPERATOR

RIKI TRANSPORTATION INC dba BRZ

ADDRESS

8225 LECTURE AVE.

CITY, STATE, ZIP CODE

BURBANK, IL 60459

VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☒ TRUCK ☐ BUS
☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

JUGOSLAV KOVACEVIC

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YESVEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

3AKJHHR6PSUA1610

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
✓			1. BRAKE SYSTEM	✓			6. SAFE LOADING	✓			12. WINDSHIELD GLAZING
✓			a. Service Brakes	✓			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
✓			b. Parking Brake System				b. Front End Structure	✓			13. WINDSHIELD WIPERS
✓			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	✓			No missing, damaged, or inoperable wipers.
✓			d. Brake Hose				7. STEERING MECHANISM	✓			14. MOTORCOACH SEATS
✓			e. Brake Tubing				a. Steering Wheel Free Play	✓			Seats securely fastened to the vehicle structure.
✓			f. Low Pressure Warning Device				b. Steering Column				15. REAR IMPACT GUARD
✓			g. Tractor Protection Valve				c. Front Axle Beam/All Other Steering Components				In place, securely attached, proper size, proper placement (see 393.86).
✓			h. Air Compressor				d. Steering Gear Box				16. OTHER
✓			i. Electric Brakes				e. Pitman Arm				List any other condition(s) which may prevent safe operation of this vehicle.
✓			j. Hydraulic Brakes				f. Power Steering				
✓			k. Vacuum Systems				g. Ball and Socket Joints				
✓			l. Antilock Brake System				h. Tie Rods and Drag Links				
✓			m. Automatic Brake Adjusters				i. Nuts				
✓			2. COUPLING DEVICES				j. Steering System				
✓			a. Fifth Wheels				8. SUSPENSION				
✓			b. Pintle Hooks				a. Axle Positioning Parts				
✓			c. Drawbar/Towbar Eye				b. Spring Assembly				
✓			d. Drawbar/Towbar Tongue				c. Torque, Radius or Tracking Components				
✓			e. Safety Devices				9. FRAME				
✓			f. Saddle-Mounts				a. Frame Members				
✓			3. EXHAUST SYSTEM				b. Tire and Wheel Clearance				
✓			a. No leaks forward of/directly below the driver/sleeper compartment.				c. Adjustable Axle Assemblies (Sliding Subframes)				
✓			b. Bus: No leaking/discharging in violation of standard.				10. TIRES				
✓			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				a. Steer-Axle Tires				
✓			4. FUEL SYSTEM				b. All Other Tires				
✓			a. No visible leak.				c. Speed-Restricted Tires				
✓			b. Fuel Tank Filler Cap				11. WHEELS AND RIMS				
✓			c. Fuel tank securely attached.				a. Lock or Side Ring				
✓			5. LIGHTING DEVICES				b. Wheels and Rims				
✓			All required lights/reflectors operable.				c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.