

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
64871433	723
DATE 01/16/23	

MOTOR CARRIER OPERATOR Zig, Freight Inc dba Royal 3 Inc	INSPECTOR'S NAME (PRINT OR TYPE) Jugoslav Kovalevic
ADDRESS 6850 W. 63rd St	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. YES
CITY, STATE, ZIP CODE Chicago, IL 60638	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 3AKJHHR6ASM25505
VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED			
OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM			
✓			a. Service Brakes
✓			b. Parking Brake System
✓			c. Brake Drums or Rotors
✓			d. Brake Hose
✓			e. Brake Tubing
			f. Low Pressure Warning Device
			g. Tractor Protection Valve
N/A			h. Air Compressor
			i. Electric Brakes
			j. Hydraulic Brakes
✓			k. Vacuum Systems
✓			l. Antilock Brake System
			m. Automatic Brake Adjusters
2. COUPLING DEVICES			
N/A			a. Fifth Wheels
✓			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
✓			d. Drawbar/Towbar Tongue
✓			e. Safety Devices
N/A			f. Saddle-Mounts
3. EXHAUST SYSTEM			
N/A			a. No leaks forward of/ directly below the driver/ sleeper compartment.
N/A			b. Bus: No leaking/ discharging in violation of standard.
N/A			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
4. FUEL SYSTEM			
N/A			a. No visible leak.
			b. Fuel Tank Filler Cap
			c. Fuel tank securely attached.
5. LIGHTING DEVICES			
✓			All required lights/reflectors operable.
6. SAFE LOADING			
			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
			b. Front End Structure
			c. Intermodal Container Securement Devices
7. STEERING MECHANISM			
			a. Steering Wheel Free Play
			b. Steering Column
			c. Front Axle Beam/All Other Steering Components
			d. Steering Gear Box
			e. Pitman Arm
			f. Power Steering
			g. Ball and Socket Joints
			h. Tie Rods and Drag Links
			i. Nuts
			j. Steering System
8. SUSPENSION			
			a. Axle Positioning Parts
			b. Spring Assembly
			c. Torque, Radius or Tracking Components
9. FRAME			
			a. Frame Members
			b. Tire and Wheel Clearance
			c. Adjustable Axle Assemblies (Sliding Subframes)
10. TIRES			
			a. Steer-Axle Tires
			b. All Other Tires
			c. Speed-Restricted Tires
11. WHEELS AND RIMS			
			a. Lock or Side Ring
			b. Wheels and Rims
			c. Fasteners
			d. Welds
12. WINDSHIELD GLAZING			
			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
13. WINDSHIELD WIPERS			
			No missing, damaged, or inoperable wipers.
14. MOTORCOACH SEATS			
			Seats securely fastened to the vehicle structure.
15. REAR IMPACT GUARD			
			In place, securely attached, proper size, proper placement (see 393.86).
16. OTHER			
			List any other condition(s) which may prevent safe operation of this vehicle.
			PASS

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.