ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD										
REP NUM		FLEET UNIT NUMBER								
6830	4435	723								
DATE	1/21	/2025								

MOTOR CARRIER OPERATOR ZIGI FREIGHT INC dba ROYAL3 INC	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOVACEVIC					
ADDRESS 6850 W. 63rd STREET	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES					
CHICAGO, IL 60638	VEHICLE INDETIFICATION (✓ AND COMPLETE) □LIC.PLATE NO. ☑ VIN □OTHER 3AKJHHDR6MSMZ5505					
VEHICLE TYPE ■ TRACTOR □ TRAILER □ TRUCK □ BUS □ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)					

			·								
						VEHICLE	COMPONENTS INSPECTED				
ОК	NEEDS REPAIR	REPAIRED DATE	ITEM	ОК	NEEDS REPAIR	REPAIRED DATE	ITEM	ОК	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHEILD GLAZING
			a. Service Brakes b. Parking Brake System c. Brake Drums or Rotors		0		a. Vehicle parts, load, dunnage, spare tire, etc., secured.		0		No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			d. Brake Hose			N/A	b. Front End Structure				13. WINDSHEILD WIPERS
			e. Brake Tubbing f. Low Pressure Warning		0	N/A	c. Intermodal Container Securement Devices	☑	0		No missing, Damaged, or inoperable wipers.
			Device				7. STEERING MECHANISM				14. MOTORCOACH SEATS
			g. Tractor Protection Valve				a. Steering Wheel Free Play				Seats securely fastened to the vehicle
			h. Air Compressor				b. Steering Column				structure.
		N/A	i. Electric Brakes				c. Front Axle Beam/All				15. REAR IMPACT GUARD
		N/A	j. Hydraulic Brakes				Other Steering Components				In place convenient attached properties
		N/A	k. Vakum Systems				d. Steering Gear Box			N/A	In place, securely attached, proper size, proper placement (see 393.86).
			I. Antilock Brake System				e. Pitman Arm				
			m. Automatic Brake Adjusters				f. Power Steering				16. OTHER
			2. COUPLING DEVICES				g. Ball and Socket Joints				List any other condition(s) which may prevent safe
			a. Fifth Wheels				h. Tie Rods and Drag Links				operation of this vehicle.
		N/A	b. Pintle Hooks				i. Nuts				
		N/A	c. Drawbar/Towbar Eye				j. Streering System				
		N/A	d. Drawbar/Towbar Tongue				8. SUSPENSION				
			e. Safety Devices				a. Axle Positioning Parts				
			f. Saddle-Mounts				b. Spring Assembly				
		I	a. No leaks forward of/				 c. Torque, Radius or Tracking Components 				
_			directly below the driver/				0. 50445				
			sleeper compartment.				9. FRAME				W PASSER //
			b. Bus: No leaking/				a. Frame Members				// NAAFD
			discharging in violation of				b. Tire and Wheel Clearancec. Adjustable Axle				
		N/A	standard. c. Unlikely to burn, char,			N/A	Assemblies (Sliding Subframes)				
			or damage the electrical				10. TIRES				
-			wiring, fuel supply, or any combustible part of vehicle.				a. Steer-Axle Tires				
			4. FUEL SYSTEM				b. All Other Tires				
			a. No visible Leak.			N/A	c. Speed-Restricted Tires				
			b. Fuel tank filler cap			,,,,,,	11. WHEELS AND RIMS				
			c. Fuel tank securely attached.				a. Lock or Side Ring				
			5. LIGHTING DEVICES				b. Wheels and Rims				
			a. All required light/reflectors				c. Fasteners				
			operable.				d. Welds				
	INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: VOK, NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, REPAIRED DATE										

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.