

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT
NUMBER

FLEET UNIT NUMBER

67129234

724

DATE

01/14/25

MOTOR CARRIER OPERATOR

Zigi Freight Inc dba Royal 3 Inc

ADDRESS

6850 W. 63rd St

CITY, STATE, ZIP CODE

Chicago, IL 60638

VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS

☐ (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)

Jugoslav Kovacevic

THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.

☒ YES

VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER

3AKJHHPK8N9125506

INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			b. Parking Brake System	☒			b. Front End Structure	☒			13. WINDSHIELD WIPERS
☒			c. Brake Drums or Rotors	☒			c. Intermodal Container Securement Devices	☒			No missing, damaged, or inoperable wipers.
☒			d. Brake Hose	☒						14. MOTORCOACH SEATS	
☒			e. Brake Tubing	☒						Seats securely fastened to the vehicle structure.	
☒			f. Low Pressure Warning Device	☒						15. REAR IMPACT GUARD	
☒			g. Tractor Protection Valve	☒						In place, securely attached, proper size, proper placement (see 393.86).	
☒			h. Air Compressor	☒						16. OTHER	
☒			i. Electric Brakes	☒						List any other condition(s) which may prevent safe operation of this vehicle.	
☒			j. Hydraulic Brakes	☒							
☒			k. Vacuum Systems	☒							
☒			l. Antilock Brake System	☒							
☒			m. Automatic Brake Adjusters	☒							
			2. COUPLING DEVICES				7. STEERING MECHANISM				
☒			a. Fifth Wheels	☒			a. Steering Wheel Free Play	☒			
☒			b. Pintle Hooks	☒			b. Steering Column	☒			
☒			c. Drawbar/Towbar Eye	☒			c. Front Axle Beam/All Other Steering Components	☒			
☒			d. Drawbar/Towbar Tongue	☒			d. Steering Gear Box	☒			
☒			e. Safety Devices	☒			e. Pitman Arm	☒			
☒			f. Saddle-Mounts	☒			f. Power Steering	☒			
			3. EXHAUST SYSTEM				g. Ball and Socket Joints	☒			
☒			a. No leaks forward of/ directly below the driver/sleeper compartment.	☒			h. Tie Rods and Drag Links	☒			
☒			b. Bus: No leaking/discharging in violation of standard.	☒			i. Nuts	☒			
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒			j. Steering System	☒			
			4. FUEL SYSTEM				8. SUSPENSION				
☒			a. No visible leak.	☒			a. Axle Positioning Parts	☒			
☒			b. Fuel Tank Filler Cap	☒			b. Spring Assembly	☒			
☒			c. Fuel tank securely attached.	☒			c. Torque, Radius or Tracking Components	☒			
			5. LIGHTING DEVICES				9. FRAME				
☒			All required lights/reflectors operable.	☒			a. Frame Members	☒			
							b. Tire and Wheel Clearance	☒			
							c. Adjustable Axle Assemblies (Sliding Subframes)	☒			
							10. TIRES				
							a. Steer-Axle Tires	☒			
							b. All Other Tires	☒			
							c. Speed-Restricted Tires	☒			
							11. WHEELS AND RIMS				
							a. Lock or Side Ring	☒			
							b. Wheels and Rims	☒			
							c. Fasteners	☒			
							d. Welds	☒			

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.