

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
68310802	725
DATE 02/01/2025	

MOTOR CARRIER OPERATOR 2161 FREIGHT INC DBA ROYAL 3 INC	INSPECTOR'S NAME (PRINT OR TYPE) JURISLAV KOVACEVIC
ADDRESS 6850 W 63rd St	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE CHICAGO, IL 60638	VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 3AKJHHDRXMSM25507
VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM											
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			12. WINDSHIELD GLAZING
☒			b. Parking Brake System				b. Front End Structure				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices	☒			13. WINDSHIELD WIPERS
☒			d. Brake Hose								No missing, damaged, or inoperable wipers.
☒			e. Brake Tubing								14. MOTORCOACH SEATS
☒			f. Low Pressure Warning Device								Seats securely fastened to the vehicle structure.
			g. Tractor Protection Valve								15. REAR IMPACT GUARD
			h. Air Compressor								In place, securely attached, proper size, proper placement (see 393.86).
			i. Electric Brakes								16. OTHER
			j. Hydraulic Brakes								List any other condition(s) which may prevent safe operation of this vehicle.
			k. Vacuum Systems								
			l. Antilock Brake System								
			m. Automatic Brake Adjusters								
2. COUPLING DEVICES											
☒			a. Fifth Wheels	☒			a. Axle Positioning Parts				
			b. Pintle Hooks	☒			b. Spring Assembly				
			c. Drawbar/Towbar Eye	☒			c. Torque, Radius or Tracking Components				
			d. Drawbar/Towbar Tongue								
			e. Safety Devices								
			f. Saddle-Mounts								
3. EXHAUST SYSTEM											
☒			a. No leaks forward of/ directly below the driver/ sleeper compartment.								
			b. Bus: No leaking/ discharging in violation of standard.								
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.								
4. FUEL SYSTEM											
☒			a. No visible leak.	☒			a. Frame Members				
☒			b. Fuel Tank Filler Cap	☒			b. Tire and Wheel Clearance				
☒			c. Fuel tank securely attached.				c. Adjustable Axle Assemblies (Sliding Subframes)				
5. LIGHTING DEVICES											
☒			All required lights/reflectors operable.								
6. SAFE LOADING											
7. STEERING MECHANISM											
8. SUSPENSION											
9. FRAME											
10. TIRES											
11. WHEELS AND RIMS											

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.