

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

REPORT NUMBER	FLEET UNIT NUMBER
G10470320	732
DATE	12/31/2024

MOTOR CARRIER OPERATOR ZIGI FREIGHT INC DBA ROYAL 3 INC	INSPECTOR'S NAME (PRINT OR TYPE) JUGOSLAV KOLACEVIC
ADDRESS 6850 W 63RD ST	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☒ YES
CITY, STATE, ZIP CODE CHICAGO, IL 60638	VEHICLE IDENTIFICATION (☒ AND COMPLETE) ☐ LIC. PLATE NO. ☒ VIN ☐ OTHER 3AKJHHFG2K3HM3997
VEHICLE TYPE ☒ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☐ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
1. BRAKE SYSTEM				6. SAFE LOADING				12. WINDSHIELD GLAZING			
☒			a. Service Brakes	☒			a. Vehicle parts, load, dunnage, spare tire, etc., secured.	☒			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
☒			b. Parking Brake System	☒			b. Front End Structure	☒			13. WINDSHIELD WIPERS
☒			c. Brake Drums or Rotors	☒			c. Intermodal Container Securement Devices	☒			No missing, damaged, or inoperable wipers.
☒			d. Brake Hose	☒			7. STEERING MECHANISM	☒			14. MOTORCOACH SEATS
☒			e. Brake Tubing	☒			a. Steering Wheel Free Play	☒			Seats securely fastened to the vehicle structure.
☒			f. Low Pressure Warning Device	☒			b. Steering Column	☒			15. REAR IMPACT GUARD
☒			g. Tractor Protection Valve	☒			c. Front Axle Beam/All Other Steering Components	☒			In place, securely attached, proper size, proper placement (see 393.86).
☒			h. Air Compressor	☒			d. Steering Gear Box	☒			16. OTHER
☒			i. Electric Brakes	☒			e. Pitman Arm	☒			List any other condition(s) which may prevent safe operation of this vehicle.
☒			j. Hydraulic Brakes	☒			f. Power Steering	☒			
☒			k. Vacuum Systems	☒			g. Ball and Socket Joints	☒			
☒			l. Antilock Brake System	☒			h. Tie Rods and Drag Links	☒			
☒			m. Automatic Brake Adjusters	☒			i. Nuts	☒			
2. COUPLING DEVICES				8. SUSPENSION							
☒			a. Fifth Wheels	☒			a. Axle Positioning Parts	☒			
☒			b. Pintle Hooks	☒			b. Spring Assembly	☒			
☒			c. Drawbar/Towbar Eye	☒			c. Torque, Radius or Tracking Components	☒			
☒			d. Drawbar/Towbar Tongue	☒			9. FRAME	☒			
☒			e. Safety Devices	☒			a. Frame Members	☒			
☒			f. Saddle-Mounts	☒			b. Tire and Wheel Clearance	☒			
3. EXHAUST SYSTEM				10. TIRES							
☒			a. No leaks forward of/directly below the driver/sleeper compartment.	☒			a. Steer-Axle Tires	☒			
☒			b. Bus: No leaking/discharging in violation of standard.	☒			b. All Other Tires	☒			
☒			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	☒			c. Speed-Restricted Tires	☒			
4. FUEL SYSTEM				11. WHEELS AND RIMS							
☒			a. No visible leak.	☒			a. Lock or Side Ring	☒			
☒			b. Fuel Tank Filler Cap	☒			b. Wheels and Rims	☒			
☒			c. Fuel tank securely attached.	☒			c. Fasteners	☒			
5. LIGHTING DEVICES								d. Welds	☒		
☒			All required lights/reflectors operable.	☒							

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ☒ OK, ☒ NEEDS REPAIR, ☒ IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.